



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLF 6241H

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	TO REPAIR SEE LABOUR	\$780.00	\$0.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$913.00	\$0.00
	LESS 25.00% DISCOUNT		(\$423.25)	\$0.00
			\$1,269.75	\$0.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO LABOUR CHARGE FOR REMOVING REAR BUMPER AND END PANEL OUT TO FACILITATE REPLACEMENT OF DAMAGED PART. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR END PANEL		\$500.00	\$200.00
	TO RESPRAY REAR BUMPER AND END PANEL		\$500.00	\$400.00
			\$1,000.00	\$600.00
GRAND TOTAL			\$2,269.75	\$600.00
	RECOMMENDED COST OF REPAIRS			\$600.00
Report Ref No: CS/LIP24090060/Unh3				

MARKET VALUE: \$34,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$21,438.00=NETT VALUE: \$12,562.00

## CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.