



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24090060/Unh3
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	12/09/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLH 8784J	Veh. Inspected	SLF 6241H
Policy No.	-	Coverage	0
Claim No.	AVS24/2734	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	03/09/2024

2. Vehicle Details

Make & Model	TOYOTA COROLLA ALTIS (A)	C.C	1598
Engine No.	1ZRY284953	Year of Reg.	01/09/2016
Chassis No.	MR053REH104549956	Colour	SILVER
Odometer	81139 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/45R17	MICHELIN	6
L/H Front Tyre	215/45R17	MICHELIN	6
R/H Rear Tyre	215/45R17	MICHELIN	6
L/H Rear Tyre	215/45R17	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/09/2024	Inspection Date	04/09/2024
Survey held at	AUTOBACS CAR CARE (S) PTE LTD 8 KAKI BUKIT AVENUE 4 #08-40/45/46 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days