

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 08102600F

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

Not Authorized
L12mp & 4550h
Penny After Pain
5day

REPAIR ESTIMATE SMK9885S

No.	Qty	List Items	
1	1	Rear bumper	\$ Bu 753.10 ✓
2	2	Rear bumper side retainer	\$ Bu 313.40 X
3	2	Rear bumper inner side impact bracket	\$ Dd 10/11 266.40 ✓
4	1 set	Rear bumper clips	\$ Bu 50.00 ✓
5	2	Taillamp	\$ Bu 955.60 ✓ 477.80
6	1	Rear boot lid	\$ Bu 1,277.60 ✓
7	1	Rear boot centre top "TOYOTA" logo	\$ Bu 67.80 ✓
8	1	Rear boot RH "F" emblem	\$ Bu 54.30 ✓
9	1	Rear boot LH "PREMIO" emblem	\$ Bu 81.70 ✓
10	2	Rear boot side lamp	\$ Bu 757.80 ✓
11	1	Rear boot outer chrome handle	\$ Bu 331.60 ✓
12	1	Rear boot top lock	\$ Bu 323.75 X
13	1	Rear boot weatherstrip	\$ Bu 251.70 ✓ 50.00
14	1	Rear end panel	\$ Bu 931.75 ✓
15	1	Rear end panel top garnish	\$ Bu 189.70 ✓
			\$ 6,606.20
Less 25%			\$ 1,651.55
Total :			\$ 4,954.65

Special Nett Items

16	1 set	Rear end panel sealant	\$ Bu 60.00 30.00
17	1 set	Rear bumper reverse sensor	\$ Bu 280.00 20.00
18	1	Rear number plate	\$ Bu 50.00 X
Total :			\$ 390.00

Labour

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$ 900.00 600.00
2	To putty and spray Spray Paintings charges.	\$ 1,000.00 600.00
3	To check wirings and lightings.	\$ 40.00 20.00
4	To remove, refit reverse sensors.	\$ 80.00 50.00
5	To remove, refit rear upholstery & attachemnts.	\$ 120.00 60.00
6	To remove, refit rear boot fittings.	\$ 80.00 50.00
7	To supply and apply anti rust treatment	\$ 80.00 50.00
Total :		\$ 2,300.00

Total Parts and Labour : \$ 7,644.65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: