



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC24090064/Anh3m4(N)

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 17/01/2025

ATTN: JULIE MANGUBAT

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|----------------|----------------|------------|
| Insured Veh. | SLX 7298T | Veh. Inspected | SNN 7642L |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | MT/1293417-002 | Excess (\$) | 0.00 |
| Assign From | JURAIDAH ABBAS | Assign Date | 04/09/2024 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|------------|
| Make & Model | HYUNDAI ELANTRA | c.c | 1591 |
| Engine No. | HIDDEN | Year of Reg. | 2017 |
| Chassis No. | KMHD841CMJU508005 | Colour | BLUE |
| Odometer | 98124 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|-----------|----------|---------|
| R/H Front Tyre | 225/40R18 | TOURADOR | 6 mm |
| L/H Front Tyre | 225/40R18 | TOURADOR | 6 mm |
| R/H Rear Tyre | 225/40R18 | TOURADOR | 6 mm |
| L/H Rear Tyre | 225/40R18 | TOURADOR | 6 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|--|---------------------|-------------------------|
| Accident Date | 01/09/2024 | Inspect Date / Time | 04/09/2024 (01:09 PM) |
| Survey held at | ONE GARAGE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-33 PREMIER @ KAKI BUKIT SINGAPORE 415875 | | |

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days