

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internat	tionale Des Experts En	Automobile
1S	LIBERTY INSURA	NCE PTE LTD	Ref:	CS/LIP24090066/Aqh3m4
	ONE RAFFLES QUESINGAPORE 0485	UAY #25-01 NORTH TOWER	Date:	15/11/2024
	SINGAPORE 046363		Code:	LIP
1.		Policy Particular	s :- THIRD PARTY CLA	IM
	Insured Veh.	SJB 2198X	Veh. Inspected	GBG 4435S
	Policy No.	-	Coverage	0
	Claim No.	IVS24/1682	Excess	\$0.00
	Assign From	ANDY SEAH	Assign Date	03/09/2024
2.		Veh	nicle Details	
	Make & Model	TOYOTA DYNA	C.C	2982
	Engine No.	1KD2732397	Year of Reg.	03/08/2017
	Chassis No.	JTFAT35Y70K208531	Colour	SILVER
	Odometer	158231 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: NIL	•	
3.		Condi	itions of Tyres	
		Size	Make	Balance (mm)
	R/H Front Tyre	195R15C	YOKOHAMA	6
	L/H Front Tyre	195R15C	YOKOHAMA	6
	R/H Rear Tyre	155R12C	YOKOHAMA	6
	L/H Rear Tyre	155R12C	YOKOHAMA	6
4.		Descrip	tion of Damages	
HE	VEHICLE SUSTAI	NED DAMAGES AT THE REAR POP	RTION.	
)AN	IAGES SEE DETAI	LS.		
5.		Gener	al Information	
	Accident Date	02/09/2024	Inspection Date	10/09/2024
	Survey held at	A-TEC AUTOMOTIVE PTE LTD - 8 KAKI BUKIT AVENUE 4 #04-20 PREMIER @ KAKI BUKI SINGAPORE 415875		
			Remarks	
5a.			Kemarks	

Estimate Days of Repair