



Your Ref : SNM24D204964/C01

Date: 25<sup>th</sup> September 2024

Our Ref : CS/CTI24090067/Tnh3m4

**M/s China Taiping Insurance (S) Pte Ltd**

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLH 144J  
ACCIDENT ON 03/09/2024**

Instruction was received to inspect the vehicle Reg. No. SLH 144J. The inspection was conducted on 04/09/2024 at the premises of M/s Ding Auto Pte Ltd, 60 Jalan Lam Huat, #06-46/47 Carros Centre, Singapore 737869.

The following vehicle information was recorded:

Registration Number	: SLH 144J
Make/Model	: BMW 216D Gran Tourer Led Nav 7 Seater
Year of Registration	: 2016
Body Colour	: White
Chassis Number	: WBA2E320005B45406
Engine Capacity	: 1496 cc
Speedometer Reading	: N/A (Battery Melted)

The vehicle caught fire. The cause of fire probably due to electrical short circuit. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$	42,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$	26,003.00)
Nett Liability	S\$	15,997.00
	=====	

Vehicle Inspected By:



MUHD NAZRIL (NAZ)  
Technical Investigator  
LL.B. (Hons) London



K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.