



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION

INCIDENT NO.: /20240903/0387

FIRE REPORTED ON: 03 September 2024

TIME OF CALL: 10:15:12 hrs

STATION

COVERAGE: Bishan Fire Station

LOCATION OF FIRE:

Along the service road

Near Fun's Florist & Nursery

No. 551, Thomson Road, Singapore 298180

2. INCIDENT INFORMATION

FIRE INVOLVED: The engine compartment of a BMW car (SLH144J).

METHOD OF EXTINGUISHMENT: By members of the public using several dry powder fire extinguishers and a domestic hose reel jet before the arrival of SCDF crew.

PROBABLE CAUSE OF FIRE: Accidental (Overheating at the engine compartment)

DAMAGE OBSERVED*: As a result of the fire, the engine compartment of the car was damaged. Other parts of the car sustained varying degrees of heat, smoke, and water damage.

Parts of the road sustained varying degrees of heat, smoke, and water damage.

The bonnet of the car was forced open during firefighting operations.

3. FATALITY/INJURY INFORMATION

NAME

NRIC/FIN

DEAD/INJURIES SUSTAINED

NIL

NIL

NIL

REPORT ISSUED BY:

MUHAMMAD FAIZAL BIN MAZLAN

for COMMISSIONER

SINGAPORE CIVIL DEFENCE FORCE

**This is based on observations made by the fire investigator incidental to his/her investigation to determine the cause and origin of the fire, and is not to be taken as an exhaustive list of damage caused by the fire.*

This is a computer generated report. No signature is required.