

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24090068/UNP3M4
Date: 07/10/2024**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1003093092
Claimant Vehicle No :	SNC163G	Insured Vehicle No :	FBN3958U
Date of Loss:	01/09/2024	Nature of Claim:	TP
		Claim No:	372088

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNC163G		
Make & Model:	MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A)	Engine No:	27491030625055
Reg. Date:	09/06/2016 (Man. Year: 2016)	Chassis No:	WDD2050402R175487
Colour:	White	Odometer:	193583 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 ZR17	Rear Tyre Size:	225/50 ZR17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,482.03	2,228.12	2,253.91	50.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,370.00	540.00	830.00	60.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,852.03	2,768.12	3,083.91	52.70
Approved Total (Overridden) (S\$)		2,200.00		
Nett Amount (S\$)	5,852.03	2,200.00	3,652.03	62.41

INSPECTION

Date of Assignment:	04/09/2024		
Date Inspected:	11/09/2024	Inspected At:	MCS GARAGE (HQ) 10 KAKI BUKIT ROAD 2 #03-25 FIRST EAST CENTRE SINGAPORE 417868
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Sep 2024)

Parts: 143 MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNC163G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed/Torn	1,829.24 FL	*1,829.24 FL
2	1		*REAR BUMPER DIFUSSER	Grazed	411.33 FL	*411.33 FL
3	1		*REAR BUMPER CHROME MOULDING	Cracked	210.23 FL	*190.68 FL
4	2		*REAR BUMPER PDC SENSORS @ 313.75	Serviceable	627.50 FL	*- FL
5	1		*REAR BUMPER TOP GUIDE	Not Necessary	161.50 FL	*- FL
6	1		*REAR BUMPER LOWER GUIDE	Not Necessary	155.90 FL	*- FL
7	2		*REAR BUMPER SIDE GUIDES - L/R @ 110.25	Not Necessary	220.50 FL	*- FL
8	2		*REAR BUMPER SIDE RETAINERS - L/R @ 105	Not Necessary	210.00 FL	*- FL
9	1		*REAR BUMPER REINFORCEMENT	Repair	817.63 FL	*- FL
10	1		*REAR FOOT - ACTIVATED SENSOR	Serviceable	280.65 FL	*- FL
11	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,974.48	2,471.25
- List Item Discount on L Items 10.00/10.00% (\$\$)	492.45	243.13
Total Parts (\$\$)	4,482.03	2,228.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO RESPRAY UNDERCOATING	New	120.00	0.00
3	TO RESPRAY PAINTING AND ETC	New	600.00	300.00
4	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	New	600.00	220.00
Gross Labour Cost (\$\$)			1,370.00	540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >