

MCS Garage

10 Kaki Bukit Road 2 #03-25, First East Centre Singapore 471868
Tel: 9270 0917 / 6538 4322

Vehicle number: SNC163G

Vehicle Made & Model: MERCEDES-BENZ C180

Qty	List Items	Amount \$
1	Rear bumper <i>De/Toin</i>	1,829.24 ✓
1	Rear bumper difusser <i>302mb</i>	411.33 ✓
1	Rear bumper chrome moulding <i>one</i>	210.23 ✓
2	Rear bumper PDC sensors @ 313.75 <i>su</i>	627.50 X
1	Rear bumper top guide <i>1n</i>	161.50 X
1	Rear bumper lower guide <i>1n</i>	155.90 X
2	Rear bumper side guides - L/R @ 110.25 <i>1n</i>	220.50 X
2	Rear bumper side retainers - L/R @ 105 <i>1n</i>	210.00 X
1	Rear bumper reinforcement <i>R</i>	817.63 X
1	Rear foot - activated sensor <i>su</i>	280.65 X
	Sub-total	4,924.48
	Less 10%	492.45
	Total List	4,432.03

Special Nett Items

1 set	Rear bumper clip <i>nee</i>	50.00 <i>40 s/w</i>
		50.00

Labour charges

To check rear electrical wiring	50.00 <i>20</i>
To respray undercoating	11 120.00 X
To respray painting and etc	600.00 <i>300</i>
Panel beating, cut, weld remove & replacing above parts	600.00 <i>220</i>
Total Labour	1,370.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 5,852.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before repairing
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

not Authorised
nee
119/24
1/5 @ 2200
2 days
Tuohphatthay

P-2431-25
102
2188.13
40
540