



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24090073/Uvp3e2
50 RAFFLES PLACE #03-03	Date:	13/09/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJC 6879H	Veh. Inspected	SMG 4119A
Policy No.	D24MTPV01002080	Coverage	0
Claim No.	CMTD2402854	Excess	\$0.00
Assign From	THELMA	Assign Date	04/09/2024

2. Vehicle Details

Make & Model	HONDA HRV (A)	C.C	1496
Engine No.	L15B5670893	Year of Reg.	19/12/2018
Chassis No.	JHMRU1830JX200891	Colour	BLACK
Odometer	40620 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60R16	YOKOHAMA	6
L/H Front Tyre	215/60R16	YOKOHAMA	6
R/H Rear Tyre	215/60R16	YOKOHAMA	6
L/H Rear Tyre	215/60R16	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/09/2024	Inspection Date	10/09/2024
Survey held at	SPEEDWERKZ PTE LTD 1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY@KAKI BUKIT, SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days