

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS24090074/EVP3M4**Date:** 09/06/2025REFERENCE

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** SLQ30G **Insured Vehicle No :** SLF4066K

Date of Loss: 01/09/2024 Nature of Claim: TP Claim No: DMPC2401157H/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ30G**

Make & Model: AUDI R8, 5.2 FSI QU R TRONIC (A) Engine No: BUJ005384

Reg. Date: 28/02/2013 (Man. Year: 2010) Chassis No: WUAZZZ424BN001349

Colour: White Odometer: 33676 km

Engine Capacity: 5204 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35 ZR19 Rear Tyre Size: 305/30 ZR19

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	28,237.00	4,449.00	23,788.00	84.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,280.00	4,380.00	1,900.00	30.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>34,517.00</b>	<b>8,829.00</b>	<b>25,688.00</b>	<b>74.42</b>
<b>+ GST 9.00/9.00% (S\$)</b>	<b>3,106.53</b>	<b>794.61</b>	<b>2,311.92</b>	<b>74.42</b>
<b>Nett Amount (S\$)</b>	<b>37,623.53</b>	<b>9,623.61</b>	<b>27,999.92</b>	<b>74.42</b>

INSPECTION

Date of Assignment: 04/09/2024

Date Inspected: 27/09/2024 Inspected At: PREMIUM AUTOMOBILES PTE LTD  
55 UBI ROAD 1  
SINGAPORE 408699

Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$18,151.00 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jun 2025)
Parts:	M1-COUPE	AUDI R8 5.2 FSI QU R TRONIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ30G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	* Check	12,439.00 FS	*- FS
2	1		*REAR BUMPER SPOILER	Cut	3,704.00 FS	*3,704.00 FS
3	2		*REAR BUMPER GRILLE - LH / RH	Not Necessary	2,350.00 FS	*- FS
4	1		*REAR BUMPER TRIMS - GLOSSY BLACK	Not Necessary	950.00 FS	*- FS
5	1		*REAR BUMPER GRILLE - LOWER	* Check	102.00 FS	*- FS
6	2		*REAR BUMPER SPOILER AIR GUIDE - LH / RH LOWER	Not Necessary	204.00 FS	*- FS
7	2		*REAR BUMPER TRIM - LH / RH	Not Necessary	202.00 FS	*- FS
8	1		*REAR BUMPER TOP COVER	Not Necessary	1,931.00 FS	*- FS
9	1		*REAR REINFORCEMENT BEAM	* Check	2,900.00 FS	*- FS
10	2		*REAR REINFORCEMENT BEAM BRACKET - LH / RH	* Check	700.00 FS	*- FS
11	2		*REAR BUMPER BRACE - LH / RH UPPER	* Check	324.00 FS	*- FS
12	1		*REAR BUMPER MOUNTING	* Check	614.00 FS	*- FS
13	1		*REAR FOG LIGHT	Cut	738.00 FS	*738.00 FS
14	4		*REAR PARKING AID SENSOR SEAL RING	Necessary	7.00 FS	*7.00 FS
15	2		*REAR PARKING AID SENSOR	* Check	572.00 FS	*- FS
16	1		*SUNDRIES	* Check	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 28,237.00 4,449.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,600.00	1,300.00
2	TO RESPRAY REAR BUMPER AND REAR BUMPER MID	New	3,200.00	2,600.00
3	TO CARRY OUT DIAGNOSTIC CHECK	New	480.00	480.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,280.00</b>	<b>4,380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >