

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0654/2024/KS
DATE : 4-Sep-24
WIP : 29612

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 9/9/2024

YOUR INSURED VEH NO : SLF 4066 K

ECICS LIMITED

10 EUNOS ROAD 8

#09-04A, SINGAPORE POST CENTRE

SINGAPORE 408600

Attn: Motor Claims Dept

OWNER'S NAME : MR KENNETH NG (HUANG SHUOJIE)
ADDRESS : 25 HAZEL PARK TERRACE
#06-03
SINGAPORE 678948
TELEPHONE : HP +65 87999707
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : SP2009725023-01
VEHICLE NO : **SLQ 30 G**
MODEL CODE : AUDI R8 5.2 QU R-TRON
MODEL YEAR : 28/2/2013
ENGINE NO : BUJ005384
CHASSIS NO : WUAZZZ424BN001349
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Sep-24
PLACE OF ACCIDENT : JUNCTION OF RIVER VALLEY ROAD & CLEMENCEAU AVE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SLQ 30 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <i>1300 x 1</i>	\$ 2,600.00	<i>1390</i>
2	TO RESPRAY REAR BUMPER AND REAR BUMPER MID. <i>1 (white) 1 (black) 1300 x 1</i>	\$ 3,200.00	<i>2600</i>
3	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 480.00	<i>✓</i>
TOTAL LABOUR CHARGES		: \$ 6,280.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 30 G.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER ? (Disrupt)	1	\$ 12,439.00	
2	REAR BUMPER SPOILER (cut) / cut	1	\$ 3,704.00	
3	REAR BUMPER GRILLE - LH / RH X	2	\$ 2,350.00	
4	REAR BUMPER TRIMS - GLOSSY BLACK X	1	\$ 950.00	
5	REAR BUMPER GRILLE - LOWER ?	1	\$ 102.00	
6	REAR BUMPER SPOILER AIR GUIDE - LH / RH LOWER X	1	\$ 204.00	
7	REAR BUMPER TRIM - LH / RH X	2	\$ 202.00	
8	REAR BUMPER TOP COVER X	1	\$ 1,931.00	
9	REAR REINFORCEMENT BEAM ?	1	\$ 2,900.00	
10	REAR REINFORCEMENT BEAM BRACKET - LH / RH ?	2	\$ 700.00	
11	REAR BUMPER BRACE - LH / RH UPPER ?	2	\$ 324.00	
12	REAR BUMPER MOUNTING ?	1	\$ 614.00	
13	REAR FOG LIGHT / cut	1	\$ 738.00	
14	REAR PARKING AID SENSOR SEAL RING / M	4	\$ 7.00	
15	REAR PARKING AID SENSOR ?	2	\$ 572.00	
16	SUNDRIES ?		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 28,237.00	
TOTAL LABOUR CHARGES		:	\$ 6,280.00	
GRAND TOTAL		:	\$ 34,517.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

STERO CLKK)
27/9/24, 10.30 am

W R

P/P

by BCL sy, 5 dys

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT