

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

MS FIRST CAPITAL INSURANCE LIMITED

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

ATTN : Motor Claim Department
Your Ref No: : **SHA4588U**
Claim Type : THIRD PARTY
Accident Date : 01.09.2024

Not Approved
dispute
means
4/9/24
L/S # 7800
7 days
take the other repair

Date : 04.09.2024
Veh Reg No : **SLN2581K**
Make / Model : **KIA CERATO K3 1.6A**
Chassis No. : KNAFX411MH5697759
Engine No. : G4FGGH667941
Reg. Date : 27 Apr 2017

Estimate Repair Cost for Vehicle No. : SLN2581K

S/N	Description	Quantity	Unit	Amount
				<u>SS</u>
	HST PRICE			
1	FRONT HEADLAMP RH <i>holder one</i>	1	PCS <i>1247</i>	1523.00 ✓
2	FRONT GRILLE <i>scr</i>	1	PCS	330.00 ✓
3	FRONT BUMPER <i>Tom</i>	1	PCS	633.00 ✓
4	FRONT BUMPER REINFORCEMENT <i>2D</i>	1	PCS <i>481</i>	499.00 ✓
5	FRONT BUMPER SIDE RETAINER LH <i>11</i>	1	PCS	45.00 X
6	FRONT BUMPER SIDE RETAINER RH <i>11</i>	1	PCS	45.00 X
7	FRONT BUMPER LOGO <i>neu</i>	1	PCS	86.00 ✓
8	REAR BOOT <i>but/3uc</i>	1	PCS	1365.00 ✓
9	REAR BOOT HINGE LH <i>R</i>	1	PCS	79.00 X
10	REAR BOOT HINGE RH <i>R</i>	1	PCS	79.00 X
11	REAR BOOT LOCK <i>scr</i>	1	PCS	121.00 X
12	REAR BOT LOCK CATCH <i>11</i>	1	PCS	55.00 X
13	REAR BOOT EMBLEM "CERATO" <i>neu</i>	1	PCS <i>50</i>	64.00 ✓
14	REAR BOOT CENTRE LOGO <i>neu</i>	1	PCS <i>48</i>	59.00 ✓
15	REAR BOOT RUBBER <i>scr</i>	1	PCS	126.00 q
16	REAR BOOT LAMP LH <i>11</i>	1	PCS	819.00 q
17	REAR BOOT LAMP RH <i>11</i>	1	PCS	819.00 X
18	REAR SPARE TYRE PANEL <i>R</i>	1	PCS	650.00 q
19	REAR SPARE TYRE TOP INSULATOR <i>11</i>	1	PCS	150.00 X
20	REAR SPARE TYRE PANEL TOP COVER BOARD <i>scr</i>	1	PCS	278.00 X
21	REAR TAILLAMP LH <i>Cne</i>	1	PCS <i>675</i>	791.00 ✓
22	REAR TAILLAMP RH <i>Cne</i>	1	PCS <i>675</i>	791.00 ✓
23	REAR END PANEL <i>Body od</i>	1	PCS	334.00 ✓
24	REAR END PANEL TOP GARNISH <i>scr</i>	1	PCS	90.00 X
25	REAR END PANEL TOP GARNISH CLIPS <i>11</i>	3	PCS	13.50 X
26	REAR BUMPER <i>Tom</i>	1	PCS	678.00 ✓

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

MS FIRST CAPITAL INSURANCE LIMITED

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

ATTN : Motor Claim Department
Your Ref No: : **SHA4588U**
Claim Type : THIRD PARTY
Accident Date : 01.09.2024

Date : 04.09.2024
Veh Reg No : **SLN2581K**
Make / Model : **KIA CERATO K3 1.6A**
Chassis No. :KNAFX411MH5697759
Engine No. : G4FGGH667941
Reg. Date : 27 Apr 2017

Estimate Repair Cost for Vehicle No. : SLN2581K

S/N	Description	Quantity	Unit	Amount
27	REAR BUMPER SIDE RETAINER LH	1	PCS	set 67.00 ✓
28	REAR BUMPER SIDE RETAINER RH	1	PCS	set 67.00 ✓
29	REAR BUMPER REINFORCEMENT	1	PCS	one 361.00 ✓
30	REAR BUMPER REINFORCEMENT BRACKET LH	1	PCS	set 145.00 ✓
31	REAR BUMPER REINFORCEMENT BRACKET RH	1	PCS	set 145.00 ✓
32	REAR BUMPER LOWER PAD	1 2x1	PCS	2x1 3217.00 ✓
33	REAR BUMPER LOWER PAD BRACKET	3	PCS	NS 372.00 x
34	REAR BUMPER SIDE INNER BRACKET LH	1	PCS	11 30.00 x
35	REAR BUMPER SIDE INNER BRACKET RH	1	PCS	11 30.00 x
36	REAR BUMPER REFLECTOR LH	1 52	PCS	one 132.00 ✓
37	REAR BUMPER REFLECTOR RH	1 52	PCS	one 132.00 ✓
38	REAR BUMPER UNDER DUST COVER LH	1	PCS	twi 68.00 ✓
39	REAR EXHAUST SILENSER	1	PCS	2 657.00 x

TOTAL PARTS :	15945.50
DISCOUNT 10% :	1594.55
SUB TOTAL :	14350.95

S/N	Description	Quantity	Unit	Amount
				<u>SPECIAL NETT</u>
1	FRONT NUMBER PLATE	1	PCS	set 50.00 40
2	REAR BUMPER SENSOR	1	SET	motor 300.00 200
3	REAR SPARE TYRE	1	PCS	11 350.00 x
4	REAR BUMPER CLIPS	10 / set	PCS	new 35.00 30

TOTAL SPECIAL NETT :	735.00
-----------------------------	---------------

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

MS FIRST CAPITAL INSURANCE LIMITED

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Date : 04.09.2024

Veh Reg No : **SLN2581K**

Make / Model : **KIA CERATO K3 1.6A**

Chassis No. :KNAFX411MH5697759

Engine No. : G4FGGH667941

Reg. Date : 27 Apr 2017

ATTN : Motor Claim Department

Your Ref No: : **SHA4588U**

Claim Type : THIRD PARTY

Accident Date : 01.09.2024

Estimate Repair Cost for Vehicle No. : SLN2581K

S/N	Description	Quantity	Unit	Amount
<u>LABOUR CHARGES</u>				SS
1	SUNDRIES			1- 30.00 X
2	TO PANEL BEATING			1800.00 / 200
3	TO CHECK WIRING			80.00 20
4	TO SPRAY RUST PROOFING			80.00 60
5	TO REMOVE & REPLACE BUMPER SENSOR			80.00 30
	TO REMOVE & REPLACE EXHAUST SILENSER			1- 80.00 X
6	TO SPRAY PAINTING			1200.00 1150
TOTAL LABOUR :				3350.00
GRAND TOTAL :				18435.95

FOR FOCUS AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

AUTHORIZED SIGNATURE

P-7800
102
7020.00
270
2460
9750
211
7800