

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24090078/AVP3E2
Date: 05/12/2024REFERENCEInsured/Claimant: KOH CHEE KEONG DAVID Policy No: 2100410483
Date of Loss: 02/09/2024 Nature of Claim: OD Claim No: 0816184204SGDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLM8880M**
Make & Model: AUDI A4, 1.8 TFSI MU (EU6) (A) Engine No: CJE096138
Reg. Date: 28/04/2015 (Man. Year: 2015) Chassis No: WAUZZZ8K2FA088783
Colour: Black Odometer: 148581 km
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$22,000.00
Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEYGeneral Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:CONDITION OF TYRESFront Tyre Size: 225/55 R16 Rear Tyre Size: 225/55 R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,379.00	333.12	15,045.88	97.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,132.00	1,892.00	14,240.00	88.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	31,511.00	2,225.12	29,285.88	92.94
+ GST 9.00/9.00% (S\$)	2,835.99	200.26	2,635.73	92.94
Nett Amount (S\$)	34,346.99	2,425.38	31,921.61	92.94

INSPECTIONDate of Assignment: 04/09/2024
Date Inspected: 06/09/2024 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days**Adjuster:** ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LID	Repair	4,041.00 FS	*- FS
2	1		*REAR LID ATTACHMENT PARTS	Not Necessary	87.00 FS	*- FS
3	1		*REAR LID PACKING ADHESIVE	Necessary	23.00 FS	*18.32 FS
4	1		*REAR FENDER - LH	Repair	5,395.00 FS	*- FS
5	1		*REA FUEL INSERT - RH	Not Necessary	111.00 FS	*- FS
6	1		*UNLEADED PETROL SIGN STICKER	Not Necessary	47.00 FS	*- FS
7	1		*LED TAILLIGHT - RH	Not Necessary	1,354.00 FS	*- FS
8	1		*REAR WINDSCREEN	Not Necessary	1,413.00 FS	*- FS
9	1		*REAR QUARTER GLASS - RH	Not Necessary	380.00 FS	*- FS
10	2		*PRIMER	Not Necessary	54.00 FS	*- FS
11	1		*A4 EMBLEM	Necessary	116.00 FS	*92.80 FS
12	1		*AUDI EMBLEM	Necessary	162.00 FS	*129.20 FS
13	1		*TFSI EMBLEM	Necessary	116.00 FS	*92.80 FS
14	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
15	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
16	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
17	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
18	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
19	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
20	1		*SUNDRIES	Not Necessary	1,000.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	15,379.00	333.12
--------------------------	------------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	0.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHT	New	280.00	0.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,600.00	0.00
4	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,600.00	0.00
5	TO DISMANTLE AND RENEW REAR BUMPER. TO DISMANTLE AND RENEW REAR LID. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	500.00
6	TO RESPRAY REAR LID, RHS REAR FENDER, RHS SILL PANEL, ROOF CHANNEL, REAR END PANELLING, DOOR ENTRANCE, DRAIN CHANNEL, AND FUEL FILLER FLAP	New	5,100.00	1,100.00
7	TO RENEW REAR WINDSCREEN AND RHS QUARTER GLASS. CARRY OUT WATER SEEPAGE TEST	New	980.00	0.00
8	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	New	400.00	0.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			16,132.00	1,892.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >