

ASSIGNMENT

From: _____ Date: _____
 Est: _____
 OD / TP RES / CD RES / EVA / INV / MV
 To in _____ Vehicle No: _____
 at _____
 of _____
 Insured: _____
 Policy No: **2100410483**
 Claims No: **0816184204SG**
 Sum Insured: _____ Excess: **0**
 (Client Record)
 Make of Vehicle: _____
 (Policy Condition)

Veh No: **SLM8880M** Yr Regn: **2015 April**
 Type: (M) Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Audi A4** C.D. **1798**
 Colour: **Black** A/C: Insured / Std / NI / NA
 Sp. Reading: **148581** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **WAUZZZSK2FA088783**
 Gen. Cond: (Good) Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil (S/Rim) / STD A/Rim or
 Tyre Size: F: **225/55R16**
 R: **225/55R16**

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front Rear
 R/Bal. **06** mm R/Bal. **06** mm
 L/Bal. **06** mm L/Bal. **06** mm
 D.O.A. **2/9/2024** D.O.I. **06/09/24**
 Survey held at **Premium**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear o/s
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
9/10/24	Final fig \$2225.12 confirmed by email (Red 29,285.88, 92%)
	MV: 22K
	PV: 16.3K
	Nett: 5.7K

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Date/Time, File Return to? _____
 Days Of Repair: **4**
 Resurvey No. of Trip: _____
 Survey Fee: _____
 Transportation: _____
 Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Inve (\$)
 Photos _____
 Others _____

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0665/2024/KS
DATE : 6-Sep-24
WIP : 29737

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/9/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept

OWNER'S NAME : MR CHEUNG JOE FAI
ADDRESS : 29 JURONG WEST ST41
#16-04
SINGAPORE 649411
TELEPHONE : HP +65 96656695
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 20100410483-09
VEHICLE NO : **SLM 8880 M**
MODEL CODE : AUDI A4 1.8 TFSI MU
MODEL YEAR : 28/4/2015
ENGINE NO : CJE 096138
CHASSIS NO : WAUZZZ8K2FA088783
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Sep-24
PLACE OF ACCIDENT : HANDICAP LOT AT 621 SENJA ROAD SINGAPORE 670621

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SLM 8880 M

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	280.00	X
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHT.	S/N \$	280.00	X
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	X
4	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00	X
5	TO DISMANTLE AND RENEW REAR BUMPER. TO DISMANTLE AND RENEW REAR LID. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,600.00	500
6	TO RESPRAY REAR LID, RHS REAR FENDER, RHS SILL PANEL, ROOF CHANNEL, REAR END PANELLING, DOOR ENTRANCE, DRAIN CHANNEL, AND FUEL FILLER FLAP.	\$	5,100.00	1100
7	TO RENEW REAR WINDSCREEN AND RHS QUARTER GLASS. CARRY OUT WATER SEEPAGE TEST	S/N \$	980.00	X
8	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	X
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	✓
TOTAL LABOUR CHARGES		:	\$ 16,132.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLM 8880 M.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR LID <i>Repr</i>	1	\$ 4,041.00	+
2	REAR LID ATTACHMENT PARTS <i>20% m</i>	1	\$ 87.00	X
3	REAR LID PACKING ADHESIVE <i>new</i>	1	\$ 23.00	✓
4	REAR FENDER - RH <i>Repr</i>	1	\$ 5,395.00	+
5	REAR FUEL INSERT - RH <i>30% m</i>	1	\$ 111.00	+
6	"UNLEADED" PETROL SIGN STICKER <i>30% m</i>	1	\$ 47.00	+
7	LED TAILLIGHT - RH	1	\$ 1,354.00	+
8	REAR WINDSCREEN	1	\$ 1,413.00	+
9	REAR QUARTER GLASS - RH	1	\$ 380.00	+
10	PRIMER	2	\$ 54.00	+
11	"A4" EMBLEM	1	\$ 116.00	✓
12	AUDI EMBLEM	1	\$ 162.00	-
13	"TFSI" EMBLEM	1	\$ 116.00	✓
14	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	X
15	1/4 GLASS SEALANT	S/N	\$ 100.00	X
16	METAL FILLER POWDER	S/N	\$ 280.00	X
17	ACRYLIC SEALANT	S/N	\$ 180.00	X
18	STONE CHIP	S/N	\$ 180.00	X
19	CAVITY WAX	S/N	\$ 140.00	X
20	SUNDRIES		\$ 1,000.00	?
TOTAL SPARE PARTS			: \$ 15,379.00	
TOTAL LABOUR CHARGES			: \$ 16,132.00	
GRAND TOTAL			: \$ 31,511.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adran G
SURVEYED DATE : 06/09/24.
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 04 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT