

**ASSIGNMENT**

Front: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estin: \_\_\_\_\_  
 OD / TP RES / CD RES / EVA / INV / MV  
 To in \_\_\_\_\_ Vehicle No: \_\_\_\_\_  
 at \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client Record)  
 Make of Vehicle: \_\_\_\_\_  
 (Policy Condition)

Veh No: SLM8880M Yr Regn: 2015 April  
 Type:  M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Audi A4 C.O. 1798  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 148581 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WAUZZZSK2FA088783  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: Nil /  S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 225/55R16  
 R: 225/55R16

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or \_\_\_\_\_

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repair: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 06/09/24  
 Survey held at: Premium  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear o/s  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>OO Alb</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>MV: 22K</u>
	<u>PV: 16.3K</u>
	<u>Nett: 5.7K</u>

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 Date/Time, File Return to? \_\_\_\_\_  
 Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Photos: \_\_\_\_\_  
 Others: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$)  : Interview (\$)  : Tech. Inve (\$)

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0665/2024/KS  
**DATE** : 6-Sep-24  
**WIP** : 29737

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/9/2024**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Motor Claims Dept

**OWNER'S NAME** : MR CHEUNG JOE FAI  
**ADDRESS** : 29 JURONG WEST ST41  
#16-04  
SINGAPORE 649411  
**TELEPHONE** : HP +65 96656695  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 20100410483-09  
**VEHICLE NO** : **SLM 8880 M**  
**MODEL CODE** : AUDI A4 1.8 TFSI MU  
**MODEL YEAR** : 28/4/2015  
**ENGINE NO** : CJE 096138  
**CHASSIS NO** : WAUZZZ8K2FA088783  
**MILEAGE** : KM  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 2-Sep-24  
**PLACE OF ACCIDENT** : HANDICAP LOT AT 621 SENJA ROAD SINGAPORE 670621

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SLM 8880 M**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	280.00	X
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHT.	S/N \$	280.00	X
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	X
4	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00	X
5	TO DISMANTLE AND RENEW REAR BUMPER. TO DISMANTLE AND RENEW REAR LID. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	<del>5,600.00</del>	500
6	TO RESPRAY REAR LID, RHS REAR FENDER, RHS SILL PANEL, ROOF CHANNEL, REAR END PANELLING, DOOR ENTRANCE, DRAIN CHANNEL, AND FUEL FILLER FLAP.	\$	<del>5,100.00</del>	1100
7	TO RENEW REAR WINDSCREEN AND RHS QUARTER GLASS. CARRY OUT WATER SEEPAGE TEST	S/N \$	980.00	X
8	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	X
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 16,132.00</b>	

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLM 8880 M.**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR LID <i>Repr</i>	1	\$ 4,041.00	+
2	REAR LID ATTACHMENT PARTS <i>20% m</i>	1	\$ 87.00	X
3	REAR LID PACKING ADHESIVE <i>new</i>	1	\$ 23.00	✓
4	REAR FENDER - RH <i>Repr</i>	1	\$ 5,395.00	+
5	REAR FUEL INSERT - RH <i>30% m</i>	1	\$ 111.00	+
6	"UNLEADED" PETROL SIGN STICKER <i>30% m</i>	1	\$ 47.00	+
7	LED TAILLIGHT - RH	1	\$ 1,354.00	+
8	REAR WINDSCREEN	1	\$ 1,413.00	+
9	REAR QUARTER GLASS - RH	1	\$ 380.00	+
10	PRIMER	2	\$ 54.00	+
11	"A4" EMBLEM	1	\$ 116.00	✓
12	AUDI EMBLEM	1	\$ 162.00	-
13	"TFSI" EMBLEM	1	\$ 116.00	✓
14	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	X
15	1/4 GLASS SEALANT	S/N	\$ 100.00	X
16	METAL FILLER POWDER	S/N	\$ 280.00	X
17	ACRYLIC SEALANT	S/N	\$ 180.00	X
18	STONE CHIP	S/N	\$ 180.00	X
19	CAVITY WAX	S/N	\$ 140.00	X
20	SUNDRIES		\$ 1,000.00	?
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 15,379.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 16,132.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 31,511.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adran G  
SURVEYED DATE : 06/09/24.  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : Not Authorised, 04 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT