



ZG PTE LTD

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67477100/ 67412845

Reg.No.: 201317155Z

Quotation : QT-000092

INCOME INSURANCE LIMITED

75 BRAS BASAH ROAD

INCOME CENTRE

SINGAPORE 189557

Attention: Motor Claim Department

TEL : 63462663

FAX : 63381500

Date In : 15/06/2024

Vehicle No. : SJP5231P

Make/Model : TOYOTA HARRIER

Mileage(KM) : 91,361

Ref./Remark :

Not Authorised
for
merch
19/6/24
2/5 # 7400
Telephone After 4 hrs.

S/N	Quantity	Particular	Qty	U/ Price S\$	Amount S\$
1	1	PCS SHOCK ABSORBER (L/H/F) 11	1 PCS	528.72	528.72 X
2	1	PCS LOWER ARM (L/H/F) 11	1 PCS	439.54	439.54 X
3	1	PCS STEERING KNUCKLE (FRONT) 11	1 PCS	536.14	536.14 X
4	1	PCS WHEEL BEARING (L/H/F) 11	1 PCS	511.31	511.31 X
5	1	PCS STEERING LINKAGE (L/H) 11	1 PCS	130.35	130.35 X
6	1	PCS FENDER (L/H/F) R	1 PCS	789.52	789.52 X
7	1	PCS FENDER INNER GARNISH (L/H/F) Torn	1 PCS 375.90	398.09	398.09
8	8	PCS FENDER INNER GARNISH CLIP 11	8 PCS	5.00	40.00 X
9	1	PCS FRONT BUMPER cut/Torn	1 PCS	904.00	904.00
10	10	PCS BUMPER CLIP 11	10 PCS	5.00	50.00
11	1	PCS FRONT BUMPER LIP 3/4	1 PCS	422.00	422.00
12	1	PCS FRONT BUMPER LIP (CENTRE) Torn	1 PCS	574.10	574.10
13	1	PCS BUMPER GRILLE Torn	1 PCS	329.50	329.50
14	1	PCS BUMPER SIDE RETAINER (L/H/F) one	1 PCS	128.91	128.91
15	1	PCS FRONT BUMPER SPONGE (CENTER) 11	1 PCS	95.10	95.10 X
16	1	PCS FRONT BUMPER SPONGE (L/H) Torn	1 PCS	64.52	64.52
17	1	PCS FRONT GRILLE 11	1 PCS	1,631.60	1,631.60 X
18	1	PCS HEADLIGHT (L/H) holder one	1 PCS 6840.10	10,038.60	10,038.60
19	1	PCS HEADLIGHT LOWER BRACKET (L/H) bent	1 PCS	121.64	121.64
20	1	PCS FOG LIGHT (L/H) one	1 PCS 361.60	460.00	460.00
21	1	PCS DAYLIGHT LED (L/H) one	1 PCS 907.80	1,100.10	1,100.10
22		Discount 25 %			-4,823.44
23		SubTotal (L)			14,470.30
24	1	PCS SPORT RIM (L/H/F) see	1 PCS	350.00	350.00 X
25	1	PCS TYRE (L/H/F) see	1 PCS	150.00	150.00 X
26		SubTotal (S)			500.00
27	1	X PANEL BEAT & REPAIR FRONT DAMAGE	1 400	700.00	700.00



ZG PTE LTD

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67477100/ 67412845

Reg.No.: 201317155Z

Quotation : QT-000092

INCOME INSURANCE LIMITED

75 BRAS BASAH ROAD

INCOME CENTRE

SINGAPORE 189557

Attention: Motor Claim Department

TEL : 63462663

FAX : 63381500

Date In : 15/06/2024

Vehicle No. : SJP5231P

Make/Model : TOYOTA HARRIER

Mileage(KM) : 91,361

Ref./Remark :

S/N	Quantity	Particular	Qty	U/ Price S\$	Amount S\$
28	1	X TO PUTTY AND RE-SPRAY AFFECTED PORTION	1	500 800.00	800.00
29	1	X TO CHECK UNDERCARRIAGE AND REPLACE DAMAGED PARTS	1	11 X 250.00	250.00
30	1	X TO COMPUTERISE ADJUST WHEEL ALIGNMENT	1	60 100.00	100.00
31	1	X TO PROVIDE UNDER TURFCODE	1	11 X 120.00	120.00
32	1	X TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1 x	20 50.00	50.00
33		SubTotal (LABOUR)			2,020.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE DOLLAR SIXTEEN THOUSAND NINE HUNDRED NINETY AND CENTS THIRTY ONLY

E. & O.E

Total	S\$	16,990.30
Discount	S\$	0.00
Net Total	S\$	16,990.30

Terms: C.O.D.

Customer's Signature/Co. Stamp

ZG PTE. LTD.

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.

P-11080.07
252
8310.05
980
9290.05
202
7432