

MS CAR AUTO PTE LTD

8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT
SINGAPORE 415875

TO	: INCOME	DATE	: 5/9/2024
VEHICLE NO	: FBR3064C (2020)	<i>Xiao Chen</i>	
VEHICLE MODEL	: SYM VF185		
CHASSIS NO	: RLGGAA501LDA01206		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT FENDER <i>Cracked</i>	1	\$ 110.00	\$ 110.00
2	FRONT FORK ASSY <i>Best</i>	1	\$ 750.00	\$ 750.00
3	FRONT FORK UNDER BRACKET <i>new</i>	1	\$ 250.00	\$ 250.00
4	FRONT COWLING <i>Cracked</i>	1	\$ 145.00	\$ 145.00
5	FRONT COWLING LOWER GARNISH <i>Cracked</i>	1	\$ 78.00	\$ 78.00
6	FRONT COWLING INNER SHIELD <i>Cracked</i>	1	\$ 215.00	\$ 215.00
7	FRONT SIDE COWLING <i>Cracked</i>	1	\$ 150.00	\$ 150.00
8	FRONT SIGNAL LAMP <i>Cracked</i>	1	\$ 188.00	\$ 188.00
9	BALANCER <i>Cracked</i>	1	\$ 50.00	\$ 50.00
10	FRONT WING MIRROR <i>Cracked</i>	1	\$ 128.00	\$ 128.00
11	HANDLE SHIELD <i>Cracked</i>	1	\$ 105.00	\$ 105.00
12	FRONT FOOTREST RUBBER <i>Cracked</i>	1	\$ 45.00	\$ 45.00
13	FRONT FOOTREST BRACKET <i>Best</i>	1	\$ 140.00	\$ 140.00
14	SIDE MAIN <i>Best</i>	1	\$ 115.00	\$ 115.00
15	MAIN STAND <i>new</i>	1	\$ 148.00	\$ 148.00
16	FOOT LEVER <i>Best</i>	1	\$ 80.00	\$ 80.00
17	REAR FOOTREST RUBBER <i>Cracked</i>	1	\$ 45.00	\$ 45.00
18	REAR FOOTREST BRACKET <i>Cracked</i>	1	\$ 95.00	\$ 95.00
19	SWING ARM <i>new</i>	1	\$ 558.00	\$ 558.00

TOTAL PRICE: \$ 3,395.00
LESS 10% \$ 339.50
SUB TOTAL PRICE: \$ 3,055.50

2439
2155.10

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FORK OIL <i>3/4</i>	1	\$ 40.00	\$ 40.00
2	FORK OIL SEAL <i>3/4</i>	1	\$ 30.00	\$ 30.00
3	STEERING CONE & BEARING <i>new</i>	1	\$ 120.00	\$ 120.00
4	HANDPHONE HOLDER <i>new</i>	1	\$ 100.00	\$ 100.00
5	REAR THERMAL STORAGE BAG <i>3/4</i>	1	\$ 280.00	\$ 280.00
6	REAR THERMAL STORAGE BAG BRACKET <i>3/4</i>	1	\$ 250.00	\$ 250.00
TOTAL :				\$ 820.00

240

LABOUR

	JOB	P	CE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$	400.00	200	
2	SPRAY PAINTING TO AFFECTED AREA	\$	400.00	200	
3	WIRING CHECK	\$	50.00	30	
4	TO STRAIGHTEN BODY CHASSIS	\$	300.00	X	

TOTAL: \$ 1 50.00

ESTIMATE REPORT

TOTAL PARTS COST: \$ 3,875.50

TOTAL LABOUR COST: \$ 1,150.00

TOTAL REPAIR COST: \$ 5,025.50

430

total: 2865.10

L/S: 2.21C ✓

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DATE: 2012/04/04 TIME: 10:00 AM

BY: [Signature] FOR: [Signature]

REPAIRER: [Signature]

REPAIRER: [Signature]

REPAIRER: [Signature]

REPAIRER: [Signature]

