

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 757Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID	NOT NECESSARY	980.00	-
1	BOOTLID LOGO	NOT NECESSARY	75.00	-
1	BOOTLID AVANTE EMBLEM	NOT NECESSARY	65.00	-
1	REAR BUMPER	DEFORMED	620.00	495.00
2	REAR BUMPER SIDE RETAINER @\$62.40	NOT NECESSARY	124.80	-
5	REAR BUMPER INNER BRACKET @\$30.00	NOT NECESSARY	150.00	-
1	REAR BUMPER REINFORCEMENT	CRACKED	420.00	345.00
2	REAR BUMPER REINFORCEMENT BRACKET @\$90.00	NOT NECESSARY	180.00	-
1	REAR BUMPER REINFORCEMENT SPONGE	NOT NECESSARY	180.50	-
2	TAILLAMP @\$480.00	NOT NECESSARY	960.00	-
1	REAR END PANEL	NOT NECESSARY	580.30	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	190.30	-
	LESS 20% DISCOUNT		-905.18	-168.00
			3,620.72	672.00
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	20.00	-
1	REAR END PANEL INSULATION SEALANT (SN)	NOT NECESSARY	100.00	-
			140.00	20.00
	LABOUR			
	PANEL BEATING, REMOVAL AND REPLACING PARTS.		1,000.00	200.00
	TO SPRAY PAINT AFFECTED AREA.		1,000.00	200.00
	TUFF COAT.	NOT NECESSARY	250.00	-
	WIRING CHECK.	NOT NECESSARY	100.00	-
	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR.	NOT NECESSARY	150.00	-
	REMOVE AND REFIX REVERSE SENSOR AND DISTACNE SETTING.		80.00	50.00
			2,580.00	450.00
	GRAND TOTAL		6,340.72	1,142.00

Report Ref No. CS/INC24090084/Aqh3m4(N)



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		900.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. CS/INC24090084/Aqh3m4(N)

TOTAL FOR SPARE PARTS: \$ 3,760.72 \$ 692.00 TOTAL FOR LABOUR: \$ 2,580.00 \$ 450.00 TOTAL REPAIR COST: \$ 6,340.72 \$ 1,142.00

XXX.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.