

on 4/9/24

F.T.FASTTRACK

25 KAKI BUKIT ROAD 4 #01-77 SYNERGY @ KB SINGAPORE 417800

TEL: 6749 1002 FAX NO : 6385 2138

RCB REG NO: 50233100C

Email : freddietan2010@gmail.com

MS FIRST CAPITAL INSURANCE LIMITED

6 RAFFLES QUAY

#21-00 JOHN HANCOCK TOWER

SINGAPORE 048580

TEL : 6222 2311 FAX : 6222 3547

ATTN : CLAIM DEPT

DATE : 3/9/2024

REF NO : SF0C248SM001

VEH NO.: FBS1750M

YAMAHA XSR155

RE : ESTIMATION FOR ACCIDENT INVOLVING VEH NO. FBS1750M /SMB237U ON 27/08/2024.

ITEM	QTY	DESCRIPTION	PRICE(S\$)
1	1	HANDLE BAR	Set 195.00
2	1	BALANCER (RH)	cu 40.00
3	1	BRAKE LEVER	2 cu 38.00 x
4	1	FRONT SIGNAL LAMP (RH)	cu 70.00
5	1	EXHAUST COVER	cu 118.00
6	1	EXHAUST CAP	cu 62.00
7	1	LOWER COVER (RH)	Dis 48.00
8	1	REAR FENDER	Dis 195.00
9	1	REAR FENDER BRACKET	Set 210.00
10	1	REAR SIGNAL LAMP (LH)	See Cu 70.00
11	1	REAR NO. PLATE	M/S 30.00
12	1	REAR NO. PLATE LIGHT	Set 55.00
13	1	handle switch RH - #145 Dye	
14	1	Mirror RH - #90 cu	
TOTAL PARTS			1,131.00
LESS 10%			113.10
TOTAL			1,017.90

LABOUR & MISC

TOWING FEE	90.00	70
LABOUR CHARGE	250.00	180
GRAND TOTAL :	1,357.90	



AUTHORISED SIGNATURE

Not Authorised
her
no any
h/s #1100
John ph. Henry
3 days
90096608

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

i-1258
402
1132.2
250
1382.2
202
1105