



# 友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

LKK

DATE: 19/09/2024 OUR REF: UAPL1703  
REPAIR ESTIMATE TO YOUR TOYOTA ALTIS NO: SLH4338R

TP Budget  
Veran

1 FRONT BONNET ASSY	Repair	\$ 1,332.60	X
2 FRONT BONNET HINGES	Bent	\$ 297.20	X
1 FRONT BONNET LOCK	Xtr new	\$ 286.50	X
1 FRONT R/H FENDER ASSY	Dented	\$ 965.30	745
1 FRONT R/H FENDER INNER SHIELD	Deformed	\$ 236.70	✓
8 FRONT L/H FENDER INNER SHIELD CLIPS	new	\$ 44.00	30
1 FRONT GRILLE ASSY	Cracked	\$ 551.20	✓
1 FRONT GRILLE EMBLEM	new	\$ 76.80	✓
1 FRONT SPLASH SHIELD	Repeated	\$ 136.00	X
2 FRONT HEADLAMP ASSY	Cracked	\$ 2,537.20	✓
1 FRONT SUPPORT PANEL	Repair	\$ 889.60	X
1 FRONT BRACE PANEL	Bent	\$ 154.20	✓
1 FRONT BUMPER FACE	Distorted	\$ 787.60	✓
2 FRONT BUMPER SIDE RETAINER	RH Cracked	\$ 188.00	94.30
1 FRONT BUMPER REINFORCEMENT	Dented	\$ 556.40	410
1 FRONT BUMPER CENTRE GRILLE	Deformed	\$ 233.40	✓
1 FRONT BUMPER BLACK SPONGE	Cracked	\$ 204.80	✓
10 FRONT BUMPER CLIPS	new	\$ 35.00	✓
1 FRONT R/H BUMPER FOG LAMP	Cracked	\$ 266.50	✓
1 FRONT R/H BUMPER FOG LAMP BRACKET	new	\$ 68.70	X
1 FRONT R/H BUMPER FOG LAMP OUTER COVER	cut	\$ 88.60	✓
1 FRONT RADIATOR TOP HOLDER BRACKET	Cracked	\$ 186.40	✓
1 FRONT AIR CON CONDENSOR UNIT	Xtr new	\$ 1,223.50	X
Engine Undercover	310	\$ 11,346.90	✓
	LESS 25%.....	\$ 2,836.73	
		\$ 8,510.18	

7244.90  
5433.67

**SPECIAL NETT:**

1 FRONT NUMBER PLATE (CHROME) *cut* 80 \$ 100.00 80

**LABOUR CHARGES:-**

TO SPRAY UNDERCOATING IN REPAIR		\$ 150.00	30
TO SEND VEHICLE FOR COMPUTER ALIGNMENT		\$ 120.00	X
TO DISM/REWIRE DAMAGED PORTION	2030	\$ 180.00	80
TO DISM/RENW FRONT AIR CON UNIT & GAS		\$ 220.00	60
TO PANEL BEAT DAMAGED CHASSIS FRAME PORTION AND RENEW PARTS		\$ 1,200.00	900
TO PUTTY AND RESPRAY DAMAGED PORTION		\$ 1,020.00	900
		\$ 11,480.18	

Total: 67543.67  
H/s: 56K  
05 Days

6K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: