

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 06 Sep 2024

Preliminary Advice

Insured Vehicle No	: GBL1609B		
TP Vehicle No	: YP6863G	Accident Date	: 31/08/2024
Make	: MITSUBISHI FEB21ER3SDEN	Assignment Date	: 06/09/2024
Date of Inspection	: 05/09/2024	Est. Duration of Repair	: 7
Inspection At	: VENDA ENGINEERING & TRADING PTE LTD (HQ) LEVEL 5, 8 TUAS AVENUE 18 SINGAPORE 638892		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,738.77
Revised Amount	:S\$	8,336.28
Check Items (Estimated)	:S\$	413.69
Total	:S\$	8,749.97
 Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.