

HWA SENG SPRAY PAINTING PTE LTD
 160 Sin Ming Drive
 #05-11 Sin Ming Autocity
 SINGAPORE 575722
 (COMPANY REGISTRATION NO.: 202017045G)
 TEL : 64533100
 FAX : 62669932

Date of Accident: 14/06/2024
 Your Insured
 Vehicle No.: SLV3175B
Not Withheld
61 Rm &
Heavy After Rain
5 days

ESTIMATE REPAIR COSTS TO AUDI TT REG. NO.: SME 7807 M

1pc	Rear Bumper		Bud m	SS	1462.00	✓
1pc	Rear Bumper Lower		cm		663.00	✓
1pc	Rear Bumper Sponge				485.00	✓
2pcs	Rear Bumper Absorber	(\$292.00/pc)			584.00	✓
1pc	Rear Bumper Reinforcement				863.00	✓
2pcs	Rear Parking Sensor	(\$231.00/pc)			462.00	✓
1pc	Rear Bumper Grille		cm		985.00	✓
1pc	Rear Bumper Lower Spoiler		m/i		1300.00	✓
1pc	Right Rear Exhaust Shield		in		213.00	X
2pcs	No. Plate Lamp	(\$135.80/pc)	in		271.60	X
1pc	O/S Exhaust Pipe Cutter		in		396.00	X
2pcs	Taillamp	(\$733.00/pc) <i>als cm</i>	o/s m		1466.00	✓
1pc	Rear Boot		in		5537.00	✓
1pc	Upper Lock		n		285.00	X
1pc	Lower Lock		n		45.00	X

15017.60

Less : 10%

1501.76

13515.84

LABOUR & MISC CHARGES

Panel Knocking	1300.00	<i>500</i>
Spray Painting	1400.00	<i>660</i>
Wire Checking	100.00	<i>20</i>
Labour to Remove & Install Rear Windscreen	180.00	<i>120</i>
Inner Seal	80.00	<i>30</i>
Sealant & Clip	60.00	<i>40</i>
Labour to Remove Upholstery	200.00	<i>X</i>
Labour to Install Reverse Sensor	100.00	<i>60</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TOTAL 16935.84

HWA SENG SPRAY PAINTING PTE LTD

Acknowledged by Repairer

Signature: