

Date :

INDIA INTERNATIONAL INSURANCE Pte Ltd
Attn: Motor Claims Department

Vehicle number : SMT4486X
Make and model : IONIQ 1.6 DCT HYBRID
Registration Date : 16/04/2024
Chassis number : KMHC851CVLU219690
Engine number : G4LELU538300

Claim Officer : Robyn
Job No. :
Owner name : KOMOCO CAR REI
Date of Acc : 04/09/2024
Policy number : B400002657MCY
Claim Type : tp

Items :		2nd	Estimate	Revised
1	FRT BUMPER CLIP X10	865952T500	\$ 20.00	
2	COVER-FR BUMPER	86511G2500	\$ 554.00	
3	MOULDING-FRONT BUMPER CTR,UPR	86585G2500	\$ 345.00	
4	MOULDING-FRONT BUMPER,RH	86564G2550	\$ 55.00	
5	DUCT ASSY-AIR CURTAIN,RH	86568G2500	\$ 13.00	
6	LAMP ASSY-DAY RUNNING LIGHT,RH	92208G2100	\$ 643.00	
7	PANEL-FENDER,RH	66321G2000	\$ 589.00	
8	CARRIER ASSY-FRONT END MODULE	64101G2000	\$ 950.00	
9	BEAM COMPLETE-FR BUMPER	64900G2000	\$ 1,484.00	
10	STIFFNER-FR BPR LWR	86571G2000	\$ 86.00	
11	BRACKET-FR BUMPER SIDE,RH	86514G2000	\$ 20.00	
12	LAMP ASSY-HEAD,RH	92102G2230	\$ 2,111.00	
			\$ 6,870.00	
Less 25% Discount			\$ 1,717.50	
Material total			\$ 5,152.50	

Vehicle number

Body,Paint & Labour Items :		Estimate	
1	To carry out accident body repair - FRT BUMPER / FRT FENDER / SUPPORT PANEL	\$ 2,760.00	
2	Complete putty and spray paint all affected areas - FRT BUMPER / FRT BUMPER GARNISH RHS / FRT RH FENDER / FRT BUMPER GARNISH / FRT BONNET	\$ 2,000.00	
Labour Charges:	2nd	Estimate	Revised
3	TO REALIGN FRT BOTH HEADLAMP (S.NETT)	\$ 40.00	
4	TO REPAIR FRT RH FENDER APRON (S.NETT)	\$ 460.00	
5	TO TOP UP A/C GAS (S.NETT)	\$ 140.00	
6	TO REPAIR FRT CHASIS MEMBER (S.NETT)	\$ 460.00	
7	TO RECALIBRATE FRT RADAR SENSOR (S.NETT)	\$ 460.00	
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING AFTER ACCIDENT REPAIR (S.NETT)	\$ 180.00	
9	TO PERFORM PREPROGRAMME AFTER ACCIDENT REPAIR (S.NETT)	\$ 180.00	
10	SUNDRIES	\$ 40.00	
Total Labour		\$ 6,720.00	
Total Parts		\$ 5,152.50	
Excess		\$ -	
		\$ 11,872.50	
Add GST 9%		\$ 1,068.53	
Grand Total		\$ 12,941.03	