



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SGX 6556P

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	HEADLAMP RH	SCRATCHED	\$2,712.00	\$1,992.00
1	FRONT BUMPER	TO REPAIR SEE LABOUR	\$2,278.00	\$0.00
1	FRONT BUMPER SIDE RETAINER RH	NOT NECESSARY	\$80.00	\$0.00
1	FRONT FENDER RH	BENT	\$1,350.00	\$1,265.00
1	SIDE MIRROR RH	CRACKED	\$624.00	\$624.00
1	SIDE MIRROR MOTOR RH	NOT NECESSARY	\$426.00	\$0.00
1	SIDE MIRROR COVER RH	MISSING	\$216.00	\$216.00
1	SIDE MIRROR GLASS RH	NOT NECESSARY	\$164.00	\$0.00
1	FRONT DOOR RH (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
1	REAR DOOR RH (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
1	REAR FENDER RH (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
	LESS 10.00% DISCOUNT		(\$785.00)	(\$409.70)
			\$7,065.00	\$3,687.30
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER CLIP (SN)	NOT NECESSARY	\$35.00	\$0.00
			\$35.00	\$0.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, FRONT DOOR RH, REAR DOOR RH AND REAR FENDER RH		\$800.00	\$400.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED		\$1,000.00	\$400.00
	TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION		\$90.00	\$40.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS		\$90.00	\$40.00
	TO REMOVE, REPLACE AND FOCUS HEADLAMP		\$100.00	\$30.00
			\$2,080.00	\$910.00
GRAND TOTAL			\$9,180.00	\$4,597.30



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$3,650.00
Report Ref No: CS/FCI24090091/Rqp3e2			

MARKET VALUE: \$54,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$31,179.00=NETT VALUE: \$22,821.00

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.