

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090092/RUA3Q2
Date: 06/12/2024

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D24MFL0003653
Claimant Vehicle No :	SCJ6188P	Insured Vehicle No :	YP2009H
Date of Loss:	30/08/2024	Nature of Claim:	TP
		Claim No:	MFL2024D0010630

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCJ6188P	Engine No:	30457388B38A15A
Make & Model:	BMW 216I, 1.5 (A)	Chassis No:	WBA32AN0907P01078
Reg. Date:	14/03/2024 (Man. Year: 2024)	Odometer:	6647 km
Colour:	Grey		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,353.35	1,495.55	1,857.80	55.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,186.00	2,242.00	944.00	29.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,539.35	3,737.55	2,801.80	42.85
+ GST 9.00/9.00% (S\$)	588.54	336.38	252.16	42.85
Nett Amount (S\$)	7,127.89	4,073.93	3,053.96	42.85
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		4,373.93		

INSPECTION

Date of Assignment:	12/09/2024		
Date Inspected:	12/09/2024	Inspected At:	Performance Motors Limited (HQ) 303 Alexandra Road, Singapore Singapore 159941
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD RASUL

Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2024)
Parts:	M1-MPV	BMW 216I 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCJ6188P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*REAR BUMPER CARRIER	Not Necessary	525.75 FS	*- FS
3	1		*REAR BUMPER BOTTOM TRIM PANEL (M)	Not Necessary	269.65 FS	*- FS
4	1		*REAR BUMPER PANEL PRIMED (MSP/PDC/P)	Deformed	1,415.55 FS	*1,415.55 FS
5	1		*REAR CENTRE GUIDE	Not Necessary	172.60 FS	*- FS
6	2		*ULTRASONIC SENSOR SKYSCRAPER GREY	Not Necessary	808.50 FS	*- FS
7	2		*DECOUPLING RING	Not Necessary	11.30 FS	*- FS
Total Parts (S\$)						3,353.35 1,495.55

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER AND ATTACHMENT	New	1,275.00	850.00
2	TO RESPRAY REAR BUMPER AND ATTACHMENT	New	1,557.00	1,038.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	177.00
4	TO REMOVE OLD PDC ASSEMBLY REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	177.00
Gross Labour Cost (\$\$)			3,186.00	2,242.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >