

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/III24090093/RMA3Q2**Date:** 18/06/2025**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D24MPCM001228  
**Claimant Vehicle No :** SNL9403H **Insured Vehicle No :** SMQ5786P  
 Date of Loss: 01/09/2024 Nature of Claim: TP Claim No: MPC2024D0010276

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SNL9403H**  
 Make & Model: BYD ATTO 3, 100KW SR (A) Engine No: HIDDEN  
 Reg. Date: 17/08/2023 (Man. Year: 2023) Chassis No: LGXCE4CB1P2165365  
 Colour: Grey Odometer: 13105 km  
 Engine Capacity: 0 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 215/55 R18 Rear Tyre Size: 215/55 R18  
 Front Left Side: Atlas 7 mm Rear Left Side: Atlas 7 mm  
 Front Right Side: Atlas 7 mm Rear Right Side: Atlas 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	442.00	362.00	80.00	18.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,800.00	600.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,842.00</b>	<b>2,162.00</b>	<b>680.00</b>	<b>23.93</b>
<b>+ GST 9.00/9.00% (S\$)</b>	255.78	194.58	61.20	23.93
<b>Nett Amount (S\$)</b>	<b>3,097.78</b>	<b>2,356.58</b>	<b>741.20</b>	<b>23.93</b>
<b>+ Loss of Use (3.0 x S\$60.00/day) (S\$)</b>		180.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,538.58</b>		

**INSPECTION**

Date of Assignment: 19/09/2024  
 Date Inspected: 19/09/2024 Inspected At: Vantage Automotive Limited (Alexandra)  
 305 Alexandra Road #02-01, Vantage Automotive Centre  
 Singapore 159942  
 Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD RASUL**Manager:** Daphne Lee Mooi Ngiuk*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2025)
<b>Parts:</b> M1-SUV	BYD ATTO 3 100KW SR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNL9403H)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
2	1		*TRIM LH REAR FENDER	Scratched	342.00 FS	*342.00 FS
<b>Total Parts (S\$)</b>					<b>442.00</b>	<b>362.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPAIR /PANEL BEAT REAR LH DOOR	New	600.00	450.00
2	TO REMOVE & REFIT DOOR PANEL PARTS	New	600.00	300.00
3	TO SPRAY PAINT REAR LH DOOR	New	600.00	600.00
4	TO CONDUCT ECU RE-PROGRAMMING AND CLEAR OF FAULT CODES TO ENSURE PROPER FUNCTION	New	600.00	450.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,400.00</b>
				<b>1,800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >