

305 Alexandra Road
 159942 Singapore
 Tel : 6376 8833
 Fax : 6477 7398

GST Registration No. M2-0000551-1



ESTIMATE

Estimate No.	Date Estimated	Page No.
BY 6863	13/09/2024	1 of 1
	Prepared By	
	Muhammad Danial Bin Ishak	

ESTIMATE REPAIR FOR	ACCOUNT 35
Ong Chee Siang (Wang Zhixiang)	India Int'l Insurance Pte Ltd
85 Yishun Avenue 11	64 Cecil Street #04/05
#07-31	IOB Building
Singapore 768865	Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNL9403H	LGXCE4CB1P2165365	17/08/2023	ATTO 3 100kW SR	12396

DESCRIPTION	VALUE
TO CONDUCT THIRD PARTY CLAIM AGAINST INDIA INTL INS. (SMQ5786P) DOA.01.09.24	0.00
TO REPAIR/PANEL BEAT REAR LH DOOR.	450 600.00
TO REMOVE & REFIT DOOR PANEL PARTS.	300 600.00
TO SPRAY PAINT REAR LH DOOR.	600.00
TO CONDUCT ECU RE-PROGRAMMING AND CLEAR OF FAULT CODES TO ENSURE PROPER FUNCTION .	450 600.00
SUNDRIES.	1820 20 100.00
Total Labour 1:	2,500.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
13186501-00	TRIM - LH REAR FENDER <i>SW</i>	1	380.00	10.00	342.00
Total Parts :					342 342.00

Res
HP 90000018
3 days
19/09/24
Res after repair

1820
342
\$2162
3 days #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Labour 1	S\$ 2,500.00
Parts	S\$ 342.00
Labour 2	S\$ 0.00
Excess	S\$ 0.00
Total GST @ 9%	S\$ 255.78
Grand Total	S\$ 3,097.78

Customer Name & Signature / Company Stamp _____ Date _____

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.