MY CAR CONSULTANT PTE LTD (Co Reg. No. 201605878Z) **60 JALAN LAM HUAT, CARROS CENTRE** #05-68 (\$737869) Tel: 93911482

TO

: CHINA TAIPING

: 6-Sep-24 DATE

ATTENTION

: MOTOR CLAIMS DEPT

JOB TYPE : T/P CLAIM

VEHICLE DETAILS

VEHICLE NO : SNM3845A

MODEL

: TOYOTA ALTIS

UNIT LIST TOTAL LIST

QUOTATION SUMMARY

CLAIM DETAIL: PARTS

	S/N	DESCRIPTION	QTY	PRICE	 PRICE	
	1	BONNET X K	1	\$ 1,025.00	\$ 1,025.00	
	2	BONNET LOWER LOCK × nn	1	\$ 321.00	\$ 321.00	
	3	BONNET HINGES X A^	1_	\$ 72.00	\$ 72.00	
Front portion -	4	FRONT BUMPER / BR	1	\$ 821.00	\$ 821.00	
Front portion -	5	FRONT BUMPER LOWER GRILLE / CR	1	\$ 298.00	\$ 298.00	
Front portion -	6	FRONT BUMPER SPONGE / BR	1	\$ 211.00	\$ 211.00	
	7	FRONT BUMPER UNDER COVER X MA	1	\$ 322.00	\$ 322.00	
	8	FRONT BUMPER REINFORCEMENT X /1/1	1	\$ 512.00	\$ 512.00	
	9	FRONT BUMPER SIDE RETAINER X NO	2	\$ 98.00	\$ 196.00	
	10	FRONT GRILLE TOP RUBBER X P/	1	\$ 82.00	\$ 82.00	
	11	FRONT GRILLE TOP GARNISH X nn	1	\$ 298.00	\$ 298.00	
Front portion -	12	FRONT GRILLE / (M) (Outer black)	1	\$ 698.00	\$ 698.00	
	13	FRONT GRILLE LOGO C/W SENSOR X //	1	\$ 1,125.00	\$ 1,125.00	
	14	FRONT BUMPER LOWER GRILLE $ imes$ (ℓ posts) 1	1	\$ 258.00	\$ 258.00	
	15	FRONT SUPPORT PANEL X nn	1	\$ 2,124.00	\$ 2,124.00	
	16	AIRCON CONDENSOR X 00	1	\$ 1,568.00	\$ 1,568.00	
	17	FRONT BRACE PANEL X /IVI	1	\$ 342.00	\$ 342.00	
	18	HORN \ r^	2	\$ 159.00	\$ 318.00	
	19	AIR CLEANER AIR DUCK X MM	1	\$ 251.00	\$ 251.00	
	20	RADIATOR X AA	1	\$ 1,780.00	\$ 1,780.00	
	21	RADIATOR TOP GARNISH X n/\	1	\$ 154.00	\$ 154.00	
	22	RADIATOR TOP BRACKET X M	2	\$ 98.00	\$ 196.00	
Front portion -	23	HEADLAMP (LH) / JR	21	\$ 1,985.00	\$ 3,970.00	
[24	HEADLAMP CHROME MOULDING X M	2	\$ 125.00	\$ 250.00	

1985/

581/

		,	_		1	_	1	
25	REAR BUMPER / BR	1	\$	798.00	\$	798.00	593/	
26	REAR BUMPER LOWER (1944 (544) / DEF	1	\$	570.00	\$	570.00	412	
27	REAR BUMPER SENSOR (LH) - BA X 10	21	\$	389.10	\$	778.20	Refu MISC	iter
28	REAR BUMPER REFLECTOR (LH) - B(N)	21	\$	85.00	\$	170.00	85/	
29	REAR BUMPER CHROME GARNISH X M	1	\$	298.00	\$	298.00		
30	REAR BUMPER RETAINER / OR	21	\$	105.00	\$	210.00	105/	
31	REAR BUMPER REINFORCEMENT / 00	1	\$	397.00	\$	397.00	/	
32	REAR BUMPER REINFORCEMENT BRACKET	m ₂	\$	112.00	\$	224.00		
33	BOOTLID / 00	1	\$	1,258.00	\$	1,258.00	/	
34	BOOTLID INNER TRIM X 1747	1	\$	321.00	\$	321.00		
35	BOOTLID REFLECTOR X NO	2	\$	489.00	\$	978.00		
36	BOOTLID STOPPER × ni)	4	\$	75.00	\$	300.00		
37	BOOT LID HINGE Y NO	2	\$	259.00	\$	518.00		
38	BOOTLID TOP LOCK / \$\int 1	1	\$	398.00	\$	398.00	/	
39	BOOTLID OUTER CHROME MOULDING Y M	1	\$	357.00	\$	357.00		
40	BOOTLID LOWER LOCK ✓ 1/O	1	\$	40.00	\$	40.00		
41	BOOTLID WEATHERSTRIP / (f 4	1	\$	220.00	\$	220.00	1	
42	BOOTLID LOGO / //	1	\$	75.00	\$	75.00	1	
43	BOOTLID EMBLEM 'COROLLA' / 1/14	1	\$	65.00	\$	65.00	/	
44	BOOTLID EMBLEM 'ALTIS" / N	1	\$	75.00	\$	75.00	1	
45	BOOTLID EMBLEM 'HYBRID"	1	\$	72.00	\$	72.00	/	
46	BOOTLID SENSOR X MA	1	\$	312.00	\$	312.00		
47	TAILLAMP (LH) > (M	-2/	\$	798.00	\$	1,596.00	798/	
48	TAILLAMP LOWER PANEL (LH) - M	21	\$	320.00	\$	640.00	320/	
49	REAR WINDSCREEN GLASS MOULDING	X nn	\$	112.00	\$	112.00		
50	REAR FENDER INNER COWLING X 00	2	\$	358.00	\$	716.00		
51	REAR FENDER INNER TRIM Y AN	2	\$	770.00	\$	1,540.00		
52	REAR END PANEL $\sim \mathcal{O}$	1	\$	695.00	\$	695.00	/	
53	REAR END PANEL TOP GARNISH / CFM	1	\$	280.00	\$	280.00	/	
54	REAR FLOOR PANEL / 🕖	1	\$	1,025.00	\$	1,025.00	/	
55	REAR FLOOR PANEL TOP BOARD / CM	1	\$	357.00	\$	357.00	/	
56	REAR FLOOR PANEL TOP SPONGE X nn	1	\$	358.00	\$	358.00		
57	REAR FLOOR SIDE PANEL X MA	2	\$	359.00	\$	718.00		
58	REAR EXHAUST HEAT SHIELD X NN	1	\$	360.00	\$	360.00		
							44 000 0	_

TOTAL PRICE LESS 25% SUB TOTAL PRICE \$ 32,605.20 \$ 8,151.30 \$ 24,453.90 11,003.00 -25% 8252.25

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
of the second states of		the state of the s	And the second of the second o	

			,		7
1 FRONT NUMBER PLATE / BR	1	\$ 50.00	\$	50.00	4
2 FRONT BUMPER CLIPS / M	10	\$ 6.50	\$	65.00	3
3 FRONT BUMPER LOWER GRILLE CLIP / M	8	\$ 6.50	\$	52.00	2
6 FRONT RADIATOR GRILLE CLIP / M	4	\$ 6.50	\$	26.00	1
7 FRONT SUPPORT SEALANT X M	1	\$ 80.00	\$	80.00	
8 REAR NUMBER PLATE X M	1	\$ 50.00	\$	50.00	
9 REAR BUMPER CLIPS / MC	10	\$ 6.50	\$	65.00	13
12 BOOT LID INSULATOR CLIP & In	10	\$ 6.50	\$	65.00	
13 BOOTLID STICKER / M. (FOCUS)	1	\$ 100.00	\$	100.00	3
14 TAILAMP CLIPS X An	4	\$ 8.00	\$	32.00	
15 TAILLAMP PANEL SEALANT X 10	2	\$ 60.00	\$	120.00	
16 REVERSE CAMERA X ↑↑↑	1	\$ 450.00	\$	450.00	
18 REVERSE SENSOR / BR	1	\$ 220.00	\$	220.00	2
19 REAR FENDER COWLING CLIPS X hn	12	\$ 6.50	\$	78.00	
20 REAR FENDER INNER TRIMD CLIPS X AA	12	\$ 6.50	\$	78.00	
21 REAR END PANEL TOP GARNISH CLIPS *//	M 6	\$ 6.50	\$	39.00	1
22 REAR END PANEL INSULATION SEAL / 1/4	1	\$ 150.00	\$	150.00	3
23 REAR FLOOR PANEL SEALANT / MC	1	\$ 120.00	\$	120.00	3

TOTAL

1,840.00

500

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

Front portion

Front portion Front portion Front portion

	S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
Front portion -	1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$800.00	200	
Front portion -	2	SPRAY PAINTING TO AFFECTED AREA	\$800.00	400	
,	3	WIRING CHECK	\$200.00	30	
		REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$150.00	X	
	5	RESET ENGINE TROUBLE CODE	\$300.00	X	
Front portion -	6	REFOCUS HEADLAMP BEAM	\$60.00	30	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

PANEL BEATING, REMOVAL AND			
1 REPLACING PARTS	\$1,600.00	1200	

_				
2	TO SPRAY PAINT AFFECTED AREA	\$1,400.00	800	
3	TUFF COAT	\$250.00	30	
4	WIRING CHECK	\$80.00	× Repute	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$300.00	80	
6	REMOVE AND REFIX REAR WINDSCREEN GLASS	\$120.00	X	
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$80.00	30	
9	REAR CHASSIS ALIGNMENT	\$550.00	X	
10	TRANFER BOOTLID MECHANISM	\$60.00	50	

2850

TOTAL

\$6,750.00

TOTAL PARTS COST 26,293.90 TOTAL LABOUR COST : \$ 6,750.00 TOTAL REPAIR COST : \$ 33,043.90

> Steve (LKK) Show (LKK) 6/9/14, 19.39 m L/S - 928 = 930 L/S L/S

11,602.25

L/S - 9281.80 = 9300

LKK Auto Consultants hence notify the Repairer of the following:

. To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: ...

Date: