



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758
 Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006
 E-mail: ryan@kanfs.net / patricia@kanfs.net
 Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883
 Tel: (65) 6481 5150 • Fax: (65) 6481 8683

DATE : 04-09-2024

UNITED OVERSEAS INSURANCE LTD

146 ROBINSON ROAD
 #02-01 UOI BUILDING
 SINGAPORE 068909

VEHICLE NO. : GBG4911J

ACCIDENT DATE : 02-09-2024 17:40

THIRD PARTY REF. : PROPERTY-POLE

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE GBG4911J TOYOTA DYNA

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT WINDSCREEN GLASS	650.00 <i>cuq</i>
2	1	FRONT WINDSCREEN RUBBER	115.00 <i>del</i>
3	1	FRONT WINDSCREEN PILLAR LH	395.00 ?
4	1	FRONT CORNER PANEL LH	135.00 <i>mir</i>
5	1	FRONT CORNER PANEL BRACKET LH	55.00 <i>bt</i>
6	1	FRONT GRILLE	230.00 <i>Ry</i>
7	1	FRONT GRILLE EMBLEM	35.00 X
8	8	FRONT GRILLE CLIP@\$3.50	28.00 X
9	1	FRONT HEADLAMP LH	385.00 <i>cuq</i>
10	1	FRONT BUMPER	290.00 <i>del</i>
11	1	FRONT BUMPER FOGLAMP COVER LH	55.00 <i>del</i>
12	1	FRONT BUMPER BRACKET@\$125.00	250.00 ?
13	1	FRONT STEP GARNISH LH	105.00 <i>cul</i>
14	1	FRONT SIDE MIRROR BRACKET LH	275.00 <i>bt</i>
15	1	FRONT SIDE MIRROR MOTOR LH	340.00 <i>dis</i>
16	1	FRONT SIDE MIRROR ROUND LH	95.00 <i>mis</i>
17	1	FRONT SIDE MIRROR SQUARE LH	105.00 <i>cuq</i>
18	1	FRONT SIDE MIRROR TOP ROUND COVER LH	25.00 <i>mis</i>
19	1	FRONT DOOR LH	680.00 <i>bt</i>
20	1	FRONT DOOR HINGE TOP LH	55.00 ?
21	1	FRONT DOOR HINGE LOWER LH	55.00 ?
22	1	FRONT DOOR CHECKER LH	75.00 ?
23	1	FRONT DOOR RUBBER FRT LH	95.00 ?
24	1	FRONT DOOR RUBBER LH	115.00 ?
25	1	FRONT DOOR LOCK LH	165.00 ?



簡福星摩嘜工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

VEHICLE NO. : GBG4911J
ACCIDENT DATE : 02-09-2024 17:40
THIRD PARTY REF. : PROPERTY-POLE

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
26	1	AIR CON CONDENSER	550.00 <i>bf</i>
27	1	AIR CON FAN ASSY	480.00 ?
28	1	AIR CON FAN BRACKET	100.00 ?
29	1	FRONT SHOCK ABSORBER LH	85.00 <i>x</i>
30	1	FRONT TOP ARM LH	530.00 <i>x</i>
31	1	FRONT LOWER ARM LH	350.00 <i>x</i>
32	1	FRONT KNUCKLE ARM LH	420.00 ?
33	1	FRONT KNUCKLE BEARING INNER LH	40.00 ?
34	1	FRONT KNUCKLE BEARING OUTER LH	30.00 ?
35	1	FRONT STABILIZER LINK LH	30.00 <i>x</i>
36	1	TIE ROD LH	115.00 <i>x</i>
37	1	TIE ROD END LH	140.00 <i>x</i>
38	1	STEERING RACK AND PINION	1600.00 <i>x</i>
39	1	REAR LAMP LH	125.00 <i>cur</i>
40	1	FRONT RIM LH	300.00 <i>bf</i>
41	1	REAR RIM LH	300.00 <i>dd</i>
42	1	REAR SHOCK ABSORBER LH	85.00 <i>x</i>
43	1	REAR BEARING OUTER LH	30.00 ?
44	1	REAR BEARING SMALL LH	40.00 ?
45	1	REAR SHAFT LH	540.00 <i>x</i>
			10,698.00
ADD 10 %			
			1,069.80
TOTAL (A)			
			11,767.80

SPECIAL NETT ITEMS

1	1	FRONT DOOR COMPANY PROFILE LH	20.00 <i>re</i>
2	1	ERP STICKER	20.00 <i>re</i>
3	1	FRONT NUMBER PLATE	40.00 <i>x</i>
4	1	TO FABRICATE AND REPLACE REAR CABIN BOX	10000.00 <i>bf</i>



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

VEHICLE NO. : GBG4911J
ACCIDENT DATE : 02-09-2024 17:40
THIRD PARTY REF. : PROPERTY-POLE

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
TOTAL (C)			10,080.00

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	50.00 ✓
2	1	TO CHECK ALIGNMENT	100.00 80 ✓
3	1	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	100.00 ✓
4	1	TO REMOVE/REFIT FRONT UNDERCARRIAGE LH	250.00 150 ✓
5	1	TO TRANSFER DOOR MECHANICISM TO NEW DOOR	80.00 60 ✓
6	1	TO REMOVE/REFIT DASHBOARD	240.00 200 ✓
7	1	TO REMOVE/REFIT/REFILL AIR CON GAS	100.00 ✓
8	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	980.00 800 ✓
9	1	SPRAYPAINTING CHARGES	880.00 800 ✓

TOTAL (D) 2,780.00

ESTIMATE TOTAL 24,627.80

Tan Kah 97495749 / 62563561

not authorise, Renewal Ex 1600

Tan Kah @ LKK Auto 5/9/24 @ 445pm

L/S RPR Resurvey after repair
8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

S: 0

C