



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8TH FLOOR) MAPLETREE ANSON SINGAPORE 079914	Ref: CS/AWA24090097/Eqp3e2 Date: 09/10/2024 Code: AWA
---	---

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EV 9229Z	Veh. Inspected	SMS 767S
Policy No.	AVPPSB0551912300	Coverage	0
Claim No.	CSG24VPPA00001/HLF	Excess	\$0.00
Assign From	HEW LEE FONG	Assign Date	05/09/2024

2. Vehicle Details

Make & Model	TOYOTA CAMRY HYBRID	C.C	2487
Engine No.	A25A5295029	Year of Reg.	20/03/2020
Chassis No.	JTNB23HK203052055	Colour	RED
Odometer	40271 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/45ZR18	MICHELIN	5
L/H Front Tyre	225/45ZR18	MICHELIN	5
R/H Rear Tyre	225/45ZR18	MICHELIN	5
L/H Rear Tyre	225/45ZR18	MICHELIN	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/09/2024	Inspection Date	06/09/2024
Survey held at	39 WOODLANDS CLOSE, #01-12 MEGA@WOODLANDS SINGAPORE 737856 - REPAIRER YEW TEE AUTOMOBILE TECH PL (HQ)		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days