



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24090098/Rvp3m4
16 RAFFLES QUAY	Date:	21/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4112T	Veh. Inspected	SJC 330M
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24007792MFCT	Excess	\$0.00
Assign From	HARMINDER	Assign Date	05/09/2024

2. Vehicle Details

Make & Model	TOYOTA LEXUS IS200T EXECUTIVE	C.C	1998
Engine No.	8ARZ045356	Year of Reg.	18/11/2016
Chassis No.	JTHBA1D2705030198	Colour	BLACK
Odometer	116669 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/45 ZR17	MICHELIN	6
L/H Front Tyre	225/45 ZR17	MICHELIN	6
R/H Rear Tyre	225/45 ZR17	MICHELIN	6
L/H Rear Tyre	225/45 ZR17	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/09/2024	Inspection Date	01/10/2024
Survey held at	42 TOH GUAN ROAD EAST ENTERPRISE HUB #01-79 SINGAPORE 608583 - REPAIRER: WAH HONG MOTORS & CREDIT PTE LTD		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days