



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SJC330M TOYOTA LEXUS IS200T EXECUTIVE

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Headlamp LH <i>CM</i> <i>XAN</i>		4279.00	<i>✓</i>
1	Headlamp lower bracket LH <i>XAN</i>		169.00	<i>X</i>
1	Day light LH <i>XAN</i>		2093.00	<i>X</i>
1	Center top grille <i>XAN</i>		1043.00	<i>X</i>
1	Center grille garnish <i>XAN</i>		363.00	<i>X</i>
1	Center lower grille <i>XAN</i>		979.00	<i>X</i>
1	Center grille top chrome <i>XAN</i>		278.00	<i>X</i>
1	Center grille logo badge <i>XAN</i>		664.00	<i>X</i>
1	Front bumper <i>CM</i>		1496.00	<i>1080</i>
2	Front bumper side retainer RH/LH@2*\$192 <i>XAN</i>		384.00	<i>X</i>
1	Front bumper side top bracket LH <i>XAN</i>		67.00	<i>X</i>
1	Front bumper side lower bracket LH <i>XAN</i>		61.00	<i>X</i>
1	Nozzle LH <i>CM</i>		570.00	<i>152.30</i>
1	Nozzle cover LH <i>CM</i>		69.00	<i>✓</i>
1	Front bumper towing cover <i>XAN</i>		48.00	<i>X</i>
1	Front reverse sensor (1pc) <i>SCA</i>		631.00	<i>300</i>
1	Fog lamp LH <i>XAN</i>		422.00	<i>X</i>
1	Fog lamp cover LH <i>CM</i>		275.00	<i>170.70</i>
1	Fog lamp bracket LH <i>XAN</i>		46.00	<i>X</i>
1	Front bumper inner side air duct LH <i>XAN</i>		203.00	<i>✓</i>
1	Front bumper sponge <i>CM</i>		156.00	<i>✓</i>
1	Front reinforcement <i>XAN</i>		330.00	<i>✓</i>
1	Front lower reinforcement <i>XAN</i>		1143.00	<i>X</i>
1	Front fender LH <i>XAN</i>		2045.00	<i>X</i>
1	Front fender shield LH <i>XAN</i>		332.00	<i>X</i>
1	Bonnet (Repair refer to labour)		0.00	
Part Items Total:			18146.00	
			-25%	
			-4536.50	
			13609.50	
SPECIAL NETT ITEMS				
1	Center grille clips <i>XAN</i>		30.00	
1	Front bumper clips <i>CM</i>		35.00	<i>✓</i>
1	Front fender shield clips LH <i>XAN</i>		25.00	
SN Items Total:			90.00	
Total Parts			13699.50	



Wah Heng Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SJC330M TOYOTA LEXUS IS200T EXECUTIVE

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
LABOUR			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	600.00 250	250
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00 250	250
3	To perform anti-rust treatment on affected areas	60.00 X M	X M
4	To remove and refix wiring system at accident damaged area and check for all electrical proper function	90.00 50	X M
5	To remove, replace and focus headlamp	50.00 30%	30%
6	To remove and replace front reverse sensor	100.00 40	40
Labour Total :		1700.00	
TOTAL (PARTS & LABOUR):		15399.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4655.25

35.00

570.00

5260.25

20%

4268.20

Ram

Hp 90010068

3 days

HS

01/10/24

HS - \$4,200 3 days Res after rpr