

Not Authorized
 21 Sep @ 3500h Max

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD850Y

AAD2406-070

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

15 JUN 2024

SHD850Y

VF1ABL15AUC283391

200303878K

RENAULT

LATITUDE

17/6/2024

SLW9406R/CHINA

1/3/2017

PART

LIST

1	BUMPER COVER REAR	\$	Bu	561.70	✓
1	BUMPER BRACKET CTR REAR	\$	Di	98.10	✓
1	BUMPER BRACKET SIDE LH REAR	\$	Sm	80.80	X
1	BUMPER BRACKET SIDE RH REAR	\$	Sm	82.10	X
1	BUMPER RETAINER LH REAR	\$	Pu	54.20	X
1	BUMPER RETAINER RH REAR	\$	Sm	59.80	X
1	BUMPER LOWER REAR	\$	Bel	411.90	✓
1	BUMPER BEAM REAR	\$	Pa	547.80	✓
1	BUMPER BEAM BRACKET LH REAR	\$	R	114.50	X
1	BUMPER BEAM BRACKET RH REAR	\$	Di	114.50	✓
1	BUMPER REFLECTOR LH	\$	Sm	16.60	X
1	BUMPER REFLECTOR RH	\$	Sm	16.60	X
1	BOOT REFLECTOR LAMP LH	\$	Sm	277.70	X
1	BOOT REFLECTOR LAMP RH	\$	CM	277.70	✓
1	TAILLAMP LH	\$	mg cm	401.40	✓
1	TAILLAMP RH	\$	mg cm	401.40	✓
1	OUTER PANEL REAR (End Panel)	\$	R	745.80	X
1	OUTER PANEL REAR (End Panel) TRIM	\$	nd	404.56	✓
1	BOOT REAR	\$	Pa	1,677.20	✓
1	BOOT FINISHER	\$	Sm	344.70	X
1	BOOT LOCK	\$	R	246.60	X
1	BOOT WEATHERSTRIP	\$	Sm	178.20	X
1	BOOT STRUT LH	\$	Sm	145.10	X
1	BOOT STRUT RH	\$	Sm	145.10	X
1	BOOT HINGE LH	\$	R	254.20	X
1	BOOT HINGE RH	\$	R	254.20	X
1	BOOT BADGE 'RENAULT'	\$	ma	82.40	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

AAD2406-

SHD850Y

- 1 BOOT BADGE

	\$	<i>Mr</i> 95.80 ✓
TOTAL	\$	8,090.66
10%	\$	809.07
	\$	<u>7,281.59</u>

SPECIAL NETT

1SET PARKING AID

- 1 REAR BUMPER CLIP
 1 REAR LH BUMPER RETAINER CLIP
 1 REAR RH BUMPER RETAINER CLIP
 1 BOOT STICKER TRANSCAB
 1 BOOT STICKER TEL NO
 1 REAR TAIL LAMP CLIP
 1 END PANEL INNER TRIM CLIP
 1 REAR BUMPER PROTECTOR
 2 WINDSCREEN SEALANT
 1 WINDSCREEN MOULDING
 1 WINDSCREEN INNER SPONGE SEAL

	\$	<i>Pr</i> 700.00 X
	\$	<i>nr</i> 65.00 X ✓
	\$	<i>nr</i> 65.00 X
	\$	<i>nr</i> 65.00 X
	\$	<i>nr</i> 100.00 <i>30%</i>
	\$	<i>nr</i> 100.00 <i>30%</i>
	\$	<i>nr</i> 65.00 X
	\$	<i>nr</i> 60.00 X
	\$	<i>nr</i> 180.00 <i>30%</i>
	\$	<i>nr</i> 150.00 X
	\$	<i>nr</i> 200.00 X
	\$	<i>nr</i> 130.00 X
TOTAL	\$	<u>1,880.00</u>
TOTAL PARTS	\$	<u>9,161.59</u>

LABOUR

To rust-proofing of the affected areas.

\$ 600.00 *30%*

Putty and spray painting of the affected portion.

\$ 1,200.00 *66%*

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,000.00 *50%*

To transfer of tailgate fittings and conduct water seepage test.

\$ 170.00 *60%*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 *60%*

To reinstall rear bumper parking sensor.

\$ 170.00 *60%*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD850Y

AAD2406-

To check steering geometry and computer wheel alignment \$ *220.00* X

To Transfer Of Fender Fittings, Attachments And Perform
Water Seepage Test.

\$ *170.00* X
TOTAL \$ 4,910.00

OVERALL TOTAL \$ 14,071.59

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: