

ASS. REC. BY:

REF:

CD/ CT2/ 460146/ Kua3

C

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 818,969/

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 043 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: S/HO 8504Yr Regn: 03, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Renault Latitude

c.c.

1995Colour M. Red / White

A/C:

Insured / Std / NI / NA

Sp. Reading 733955

T/Radio:

Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VIF/ABL 15 AUG 28 3391Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Sailun

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 17/6/24D.O.I. 19/6/2024

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Get BT19/6 17 Rm @ 3500/ Car

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trlp: \_\_\_\_\_

Survey Fee:

Transportation

S + RS. \$

Fin. fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Not Authorized  
Using \$3500 Max

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

**SHD850Y**

**AAD2406-070**

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

19 JUN 2024

SHD850Y

VF1ABL15AUC283391

200303878K

RENAULT

LATITUDE

17/6/2024

SLW9406R/CHINA

1/3/2017

**PART**

**LIST**

- 1 BUMPER COVER REAR
- 1 BUMPER BRACKET CTR REAR
- 1 BUMPER BRACKET SIDE LH REAR
- 1 BUMPER BRACKET SIDE RH REAR
- 1 BUMPER RETAINER LH REAR
- 1 BUMPER RETAINER RH REAR
- 1 BUMPER LOWER REAR
- 1 BUMPER BEAM REAR
- 1 BUMPER BEAM BRACKET LH REAR
- 1 BUMPER BEAM BRACKET RH REAR
- 1 BUMPER REFLECTOR LH
- 1 BUMPER REFLECTOR RH
- 1 BOOT REFLECTOR LAMP LH
- 1 BOOT REFLECTOR LAMP RH
- 1 TAILLAMP LH
- 1 TAILLAMP RH
- 1 OUTER PANEL REAR (End Panel)
- 1 OUTER PANEL REAR (End Panel) TRIM
- 1 BOOT REAR
- 1 BOOT FINISHER
- 1 BOOT LOCK
- 1 BOOT WEATHERSTRIP
- 1 BOOT STRUT LH
- 1 BOOT STRUT RH
- 1 BOOT HINGE LH
- 1 BOOT HINGE RH
- 1 BOOT BADGE 'RENAULT'

|    |       |          |   |
|----|-------|----------|---|
| \$ | Bu    | 561.70   | ✓ |
| \$ | Dit   | 98.10    | ✓ |
| \$ | Sn    | 80.80    | X |
| \$ | Sn    | 82.10    | X |
| \$ | Sn    | 54.20    | X |
| \$ | Sn    | 59.80    | X |
| \$ | Bel   | 411.90   | ✓ |
| \$ | Bn    | 547.80   | ✓ |
| \$ | R     | 114.50   | X |
| \$ | Dij   | 114.50   | ✓ |
| \$ | Sn    | 16.60    | X |
| \$ | Sn    | 16.60    | X |
| \$ | Sn    | 277.70   | X |
| \$ | CM    | 277.70   | ✓ |
| \$ | my cm | 401.40   | ✓ |
| \$ | my cm | 401.40   | ✓ |
| \$ | R     | 745.80   | X |
| \$ | nd    | 404.56   | ✓ |
| \$ | Bn    | 1,677.20 | ✓ |
| \$ | Sn    | 344.70   | X |
| \$ | R     | 246.60   | X |
| \$ | Sn    | 178.20   | X |
| \$ | Sn    | 145.10   | X |
| \$ | Sn    | 145.10   | X |
| \$ | R     | 254.20   | X |
| \$ | R     | 254.20   | X |
| \$ | mn    | 82.40    | ✓ |

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

**AAD2406-****SHD850Y**

1 BOOT BADGE

|       |    |           |          |          |
|-------|----|-----------|----------|----------|
|       | \$ | <i>Mr</i> | 95.80    | <i>✓</i> |
| TOTAL | \$ |           | 8,090.66 |          |
| 10%   | \$ |           | 809.07   |          |
|       | \$ |           | 7,281.59 |          |

**SPECIAL NETT**

1SET PARKING AID

- 1 REAR BUMPER CLIP
- 1 REAR LH BUMPER RETAINER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 BOOT STICKER TRANSCAB
- 1 BOOT STICKER TEL NO
- 1 REAR TAIL LAMP CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

|             |           |          |             |
|-------------|-----------|----------|-------------|
| \$          | <i>Pr</i> | 700.00   | <i>X</i>    |
| \$          | <i>nk</i> | 65.00    | <i>X</i>    |
| \$          | <i>nn</i> | 65.00    | <i>X</i>    |
| \$          | <i>nn</i> | 65.00    | <i>X</i>    |
| \$          | <i>nn</i> | 100.00   | <i>301n</i> |
| \$          | <i>nn</i> | 100.00   | <i>301n</i> |
| \$          | <i>nn</i> | 65.00    | <i>X</i>    |
| \$          | <i>nn</i> | 60.00    | <i>X</i>    |
| \$          | <i>nn</i> | 180.00   | <i>301n</i> |
| \$          | <i>nn</i> | 150.00   | <i>X</i>    |
| \$          | <i>nn</i> | 200.00   | <i>X</i>    |
| \$          | <i>nn</i> | 130.00   | <i>X</i>    |
| TOTAL       | \$        | 1,880.00 |             |
| TOTAL PARTS | \$        | 9,161.59 |             |

**LABOUR**

To rust-proofing of the affected areas.

\$ 600.00 *301*

Putty and spray painting of the affected portion.

\$ 1,200.00 *601*

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,000.00 *5001*

To transfer of tailgate fittings and conduct water seepage test.

\$ 170.00 *601*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 *601*

To reinstall rear bumper parking sensor.

\$ 170.00 *601*

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

**SHD850Y**

**AAD2406-**

To check steering geometry and computer wheel alignment \$ *nn* 220.00 X

To Transfer Of Fender Fittings, Attachments And Perform  
Water Seepage Test.

\$ *nn* 170.00 X  
**TOTAL \$ 4,910.00**

**OVERALL TOTAL \$ 14,071.59**

*3 days*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: