

KY AUTO PTE LTD

25 Kaki Bukit Road 4 #05-23 Synergy Building S417800

M (65) 9807 3304 Mr. Yap

F (65)

Email: kyaautosg@gmail.com

Date: 04/09/2024

D.O.A 04/09/2024

Hyundai Avante - SNS4826S

Damaged Area: Front Right Portion

Parts / Material :

1	Front bumper	187.00	215	\$	1,550.60	✓
2	Front bumper bracket RH		11	\$	128.30	X
3	Front bumper side retainer RH	95.00	one	\$	406.80	✓
4	Headlamp assy LED RH		502	\$	2,480.60	✓
5	Front bumper clips set	40	121	\$	80.00	✓
6	Headlamp lower bracket o/s RH		11	\$	245.60	X
7	Front fender Liner RHS		11	\$	303.60	X
8	Front bumper sensor		11	\$	460.30	X
9	Fog lamp cover RH	54.00	one	\$	168.60	✓
10	Front fender Liner clips set		11	\$	80.00	X
11	Steering Tie Rod RH		11	\$	328.30	X
12	Steering Tie Rod End RH		11	\$	365.40	X
13	Frt Lower arm RH		11	\$	1,360.30	X
14	Knuckle arm RH		11	\$	1,460.20	X
15	Shock absorber RH		11	\$	860.30	X
16	Front fender RH		12	\$	1,095.40	X
17	Wheel Rim		11	\$	1,280.60	X
		202	Total Parts:	\$	12,654.90	

Special Net Items :

Miscellaneous Item

Arcylic Sealant

11	\$	60.00	X
11	\$	100.00	X
Total S/N Parts :	\$	160.00	

Labour :

To Remove & Renew Front Affected Accident Areas

\$ 2,000.00 380

To Putty, Spray Paint on Front Affected Accident Areas

\$ 1,800.00 400

To remove and reinstall undercarriage

\$ 11 500.00 X

Not Accident
near
P/P = 4022.80
the photography
3 days
6/9/24

To conduct computerised wheel alignment
 To remove and reinstall wire harness. Check according to damage.
 To Conduct & reset ECU diagnostic programme
 To Rust Proof Affected Area
 To carry out spray coating

\$	11	150.00	X
\$		200.00	20
\$	17	450.00	X
\$	17	200.00	X
\$	17	800.00	X
Total Labour :		\$ 6,100.00	

TOTAL PARTS : \$ 12,654.90
TOTAL S/N PARTS: \$ 160.00
TOTAL LABOUR : \$ 6,100.00
TOTAL REPAIR COST : \$ 18,914.90

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, pending resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-4028.5
 202
3222.80
 800
4022.80

KY AUTO PTE LTD

25 Kaki Bukit Road 4 #05-23 Synergy Building S417800

M (65) 9807 3304 Mr. Yap

F (65)

Email: kyautosg@gmail.com

Date: 16/09/2024

D.O.A 04/09/2024

SUPPLEMENTARY

Hyundai Avante - SNS4826S

Damaged Area: Front Right Portion

Parts / Material:

- | | |
|---|--------------------------|
| 1 | Front bumper Air Duct RH |
| 2 | Front Bumper Moulding RH |

223.40	\$	one	328.30	/
248.50	\$	one	365.40	/

Total Parts:	\$	693.70
---------------------	-----------	---------------

(202)