

金興(興)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming Auto City

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

(S2Go: 12pm 6/9/24) FRIDAY

Your Reference : MOMVP000005772-00-000
Accident Date : 30-Aug-2024

No. : 33926

Date : 05-Sep-2024

Our Ref : 024544 / HANAH

PAGE : 1

GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVE #16-01
CENTENNIAL TOWER
Singapore 039190

ESTIMATED COST OF REPAIR FOR VOLKSWAGEN SHARAN 2.0 TSI AT (2015) SNR6798G

1 pc rear bumper - top		920.00	c <i>tu</i>
1 pc rear bumper - bottom		230.00	c <i>at</i>
2 pcs rear bumper side bracket (LH/RH)	@ S\$ 55.00	110.00	c <i>RM x LH - Run</i>
1 pc rear bumper centre bracket		105.00	c <i>89</i>
1 pc rear bumper tow cover		50.00	c <i>x</i>
1 pc rear bumper sponge		110.00	c <i>7</i>
1 pc rear bumper reinforcement		480.00	c <i>7</i>
1 pc rear bumper lower garnish		120.00	c <i>7</i>
2 pcs rear bumper lower garnish bracket (LH/RH)	@ S\$ 20.00	40.00	c <i>7</i>
1 pc rear bumper top step cover		180.00	c <i>na</i>
1 pc LH rear bumper reflector		60.00	c <i>cu</i>
2 pcs LH rear bumper parking sensor	@ S\$110.00	220.00	c <i>Run</i>
1 pc rear bumper parking sensor wireharness		190.00	c <i>2 u1</i>
6 pcs rear bumper parking sensor bracket	@ S\$ 20.00	120.00	c <i>na</i>
6 pcs rear bumper parking sensor seal	@ S\$ 3.00	18.00	c <i>na</i>
1 pc LH rear fender		1,450.00	c <i>x R</i>
1 pc LH rear fender inner shield		150.00	c <i>tu</i>
10 pcs LH rear fender inner shield clip	@ S\$ 5.00	50.00	c <i>na - 30</i>
1 pc LH rear fender top glass		290.00	c <i>x u1</i>
1 pc LH taillamp		220.00	c <i>cu</i>
1 pc LH taillamp panel		200.00	c <i>x u1</i>

Con't Page 2 ...

Press any key to continue...

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming Drive #02-18/19/20

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : MOMVP000005772-00-000
Our Ref : 024544

Page : 2

No. : 33926

1 pc LH taillamp securing element		20.00	c <i>Pen</i>
1 pc LH taillamp side cover		50.00	c <i>an</i>
1 pc tailgate		2,200.00	c <i>ht</i>
2 pcs tailgate hinges (LH/RH)	@ S\$ 85.00	170.00	c X
2 pcs tailgate damper (LH/RH)	@ S\$600.00	1,200.00	c X
1 pc tailgate lock		400.00	c X
1 pc tailgate lock cover		15.00	c X
1 pc tailgate lock catch		55.00	c X
1 pc tailgate weatherstrip		200.00	c X
1 pc tailgate inner trim		520.00	c X
1 pc tailgate logo		85.00	c <i>ner</i>
1 pc tailgate "SHANRAN" emblem		80.00	c <i>ner</i>
1 pc tailgate "2.0 TSI" emblem		65.00	c <i>ner</i>
1 pc LH tailgate lamp assy		210.00	c <i>ner</i>
1 pc rear end panel - lower		370.00	c X
1 pc rear end panel - upper		340.00	c X
1 pc rear end panel top garnish		190.00	c X
		11,483.00	
Add 10% :		1,148.30	
		12,631.30	

1 pc LH rear fender top glass sealant	<i>nn</i> X 40.00 <i>sn</i>
1 pc LH rear fender top glass damping seal	<i>nn</i> X 20.00 <i>sn</i>

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

600
1,000.00

To focus taillamps. To check rear wiring and lighting operation.

✓
50.00

To remove and refit rear windscreen glass and conduct water leak test

✓
120.00

Con't Page 3 ...

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : MOMVP000005772-00-000

Our Ref : 024544

Page : 3

No. : 33926

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

60

120.00

To remove and refit reverse sensor
assy.

50

80.00

To putty and respray on affected
portions.

1580

700

1,200.00

Total : S\$15,261.30

Singapore Dollars FIFTEEN THOUSAND TWO HUNDRED
SIXTY ONE AND CENTS THIRTY Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

Tanfik 97495749

Not Authorise 6/9/24 @ 12pm

Tanfik @ khanda.com

Ex: to be advise

L/S Resury after repair

5 days

5101.80

1580

6681.80

4/5 \$5350

5 day

X

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

edged by Repairer

ature: