

Date: 3/9/2024
Vehicle No: SNR9256J
Model: TESLA MODEL 3
Chassis: LRW3F7FS6RC205117
Reg. Year: 2024

~P# 2631

Third Party Insurer: AIG
Third Party Veh No: GBM4546Z
Date of Accident: 1/9/2024
Estimator: JONATHAN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	LH SIDE MIRROR ASSY			\$ <i>C/M</i> 532.71
	LHS MIRROR COVER			REPAIR
	LHF DOOR			REPAIR
SUB TOTAL				\$ 532.71
Less 10%				-\$ 53.27
PARTS TOTAL				\$ 479.44

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
				\$ 50.00
S/N TOTAL				\$ 50.00

LABOUR CHARGES:

To remove, replace, repair, readjust & refix Side affected areas

\$ 200.00 *1201*

To perform wiring checks on electrical systems

\$ 30.00 *201*

To remove, putty, repair, sand and respray affected areas

\$ 350.00 *2801*

LABOUR TOTAL \$ 580.00

JONATHAN TOTAL \$ 1,109.44

PARTS: \$ 479.44
LABOUR: \$ 400
TOTAL: \$ 879.44

*Not within
Penny Bp painting
2 days*

Head Office

5 Keng Chung Road Singapore 187142
Tel: (65) 8472 1313 Fax: (65) 8472 2112

Branch

2A Serangoon North Ave 5 Singapore 554800
Tel: (65) 8484 0010 Fax: (65) 8425 1002

Branch (Motor Insurance Claims)

8A 15 Ang Mo Kio Rd, Park 2A 401-02 Singapore 568047
Tel: (65) 8401 1022 Fax: (65) 8481 1011

