

HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

ESTIMATE

TP INC
Veron.

VEHICLE NO : SMG 1730 D
CHASSIS NO : ZWR800339497

MAKE / MODEL : TOYOTA NOAH
ACCIDENT DATE : 28.08.2024

NO	DESCRIPTION	QTY	AMOUNT (\$)
LIST ITEMS			
1	Rear windscreen side rubber @ \$ <i>new</i>	2	\$ 98.44 ✓
2	Rear tailgate <i>Disturbed</i>	1	\$ 1812 3174.11 ✓
3	Rear tailgate shock absorber @ \$ <i>new</i>	2	\$ 1040.29 +
4	Rear tailgate inner board <i>cracked</i>	1	\$ 762 905.05 ✓
5	Rear tailgate inner lock <i>Disturbed</i>	1	\$ 375 744.16 ✓
6	Rear tailgate inner handle <i>new</i>	1	\$ 37.49 +
7	Rear tailgate weather strip <i>Disturbed</i>	1	\$ 385 592.71 ✓
8	Rear tailgate logo <i>new</i>	1	\$ 107.29 ✓
9	Rear tailgate chrome handle <i>Disturbed</i>	1	\$ 581 1117.16 ✓
10	Rear tailgate HYBRID emblem <i>new</i>	1	\$ 76.36 ✓
11	Rear lamp @ \$ <i>RH not cut</i>	2	\$ 1370 2352.26 #2
12	Rear end panel <i>Distorted</i>	1	\$ 736 1295.01 -
13	Rear end panel top garnish <i>Disturbed</i>	1	\$ 243.45 ✓
14	Rear bumper <i>Distorted</i>	1	\$ 962.20 -
15	Rear bumper side holder @ \$ <i>new</i>	2	\$ 396.62 +
16	Rear bumper side reflector @ \$ <i>RH cracked</i>	2	\$ 86 191.82 1/2
17	Rear bumper reverse sensor @ \$ <i>Disturbed 2 pins</i>	4	\$ 380 760.00 1/2
18	Rear bumper clips <i>new</i>	1	\$ 6.35 -
19	Rear lamp lower cover @ \$ <i>RH Disturbed</i>	2	\$ 179 562.58 %
20	Rear fender inner side garnish <i>RH Disturbed</i>	2	\$ 1812 1969.31 ✓
21	Rear floor panel <i>new</i>	1	\$ 1229.92 x
22	Rear floor panel top board @ \$ <i>cracked</i>	2	\$ 891 3517.62 ✓
23	Rear tailgate lock sensor <i>cracked</i>	1	\$ 185 437.00 ✓
24	Rear end panel inner garnish <i>Disturbed</i>	1	\$ 148 427.51 ✓
25	Rear battery cover <i>Disturbed</i>	1	\$ 129 335.34 ✓
26	Rear seat bracket cover @ \$ <i>Disturbed</i>	2	\$ 129 401.22 ✓
27	Rear floor panel top carpet <i>new</i>	1	\$ 552.00 ✓
			\$ 23533.21
LESS 25% DICS			\$ 5883.30
TOTAL			\$ 17649.91

12079.31

89059.48

HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

ESTIMATE

VEHICLE NO : SMG 1730 D

CHASSIS NO : ZWR800339497

MAKE / MODEL : TOYOTA NOAH

ACCIDENT DATE : 28.08.2024

NO	DESCRIPTION	QTY	AMOUNT (\$\$)
LABOUR COST			
1	To supply rear windscreen sealant	1	\$ 50.00 ✓
2	To supply rear end panel inner sealant	1	\$ 200.00 60
3	Remove + reinstall rear windscreen	1	\$ 150.00 120
4	Remove + reinstall tailgate inner garnish	1	\$ 200.00 60
5	Remove + reinstall reverse sensor	1	\$ 150.00 50
6	Remove, replace + repair consistent to the accident	1	\$ 1600.00 800
7	Respray painting	1	\$ 1500.00 800
8	Tuff kote	1	\$ 100.00 60
TOTAL			\$ 3950.00
1900 GRAND TOTAL			\$ 21599.91

Adrian C.

L/S 09/09/24.

06 Days

total: 110959.48

L/S: 8.7K.

8.7K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: