

Wheelz 4 You

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

To: Motor Claims Department

Vehicle No: SGR7887J

Model: MERCEDES S300

Acknowledged by Repairer

Signature:

Date:

ESTIMATE For SGR7887J MERCEDES S300

not Approved
LKK motor
L/s # 5700
3 days

Date: 06/09/2024

Complete. After 14 days

QTY	Parts	Amount
1	BONNET LOGO ✓✓	\$ 268.00 X
1	RADIATOR GRILLE C19	916.46 \$ 1,076.00 X
1	RH HEADLAMP C19	2980.21 \$ 3,180.00 X
1	RH HEADLAMP LOWER BRACKET ✓✓	\$ 298.00 X
1	FRONT BUMPER C19	2020.37 \$ 2,930.00 ✓
1	RH FRONT BUMPER SIDE RETAINER YW1	122.00 \$ 151.00 ✓
1	RH HEADLAMP WASHER COVER ✓✓	\$ 247.00 X
1	RH HEADLAMP WASHER NOZZLE ✓✓	\$ 320.00 X
2	RH FRONT BUMPER SENSOR @\$281/PC ✓✓	\$ 562.00 X
4	FRONT BUMPER SENSOR ORING ✓✓	\$ 100.00 X
4	FRONT BUMPER SENSOR BRACKET ✓✓	\$ 180.00 X
1	RH FRONT FOG LAMP ✓✓	\$ 845.00 X
1	RH FRONT FENDER R	\$ 2,598.00 X
1	RH FRONT FENDER INNER SHIELD ✓✓	\$ 220.00 X
Parts Sum:		\$ 12,975.00
Parts Less 10% :		\$ 1,297.50
Parts Total:		\$ 11,677.50
Special Nett Items		
1	RADIATOR GRILLE CLIP ✓✓	\$ 40.00 X
1 set	FRONT BUMPER CLIPS ✓✓✓	\$ 40.00 ✓
1	FRONT BUMPER RIVETS ✓✓	\$ 60.00 X
1	RH FRONT FENDER INNER SHIELD CLIP ✓✓	\$ 40.00 X
Special Nett Items Total:		\$ 180.00

Labour & Misc Charges

Description	Amount
TO FOCUS HEADLAMP	\$ 50.00 20
TO REPROGRAM AND RECODE HEADLAMP MODULE	\$ ✓✓ 350.00 X
TO FIT FRONT BUMPER SENSOR ON NEW BUMPER	\$ 50.00 30
TO RESET PDC	\$ ✓✓ 350.00 X
TO RUST PROOF ON ACCIDENT DAMAGE AREA	\$ ✓✓ 250.00 X
TO PANEL BEAT AND REPLACEMENT OF PARTS	\$ 800.00 300
TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA	\$ 1,000.00 600
Labour Charges Total:	\$ 2,850.00

P. 6039.04
102
5435.14
40
950

Parts Total: \$ 11,677.50

Special Nett Items Total:	\$	180.00
Labour Charges Total:	\$	2,850.00
Total Cost Of Repair:	\$	<u>14,707.50</u>
(Non-Inclusive of GST)		