



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24090108/Avh3
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	01/10/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMS 5987R	Veh. Inspected	SNK 4708S
Policy No.	-	Coverage	0
Claim No.	BVS24/0530	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	05/09/2024

2. Vehicle Details

Make & Model	TOYOTA YARIS CROSS HYBRID	C.C	1490
Engine No.	M15AY575849	Year of Reg.	18/04/2023
Chassis No.	MXPJ103068614	Colour	YELLOW
Odometer	104475 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/65R15	YOKOHAMA	6
L/H Front Tyre	205/65R15	YOKOHAMA	6
R/H Rear Tyre	205/65R15	YOKOHAMA	6
L/H Rear Tyre	205/65R15	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/07/2024	Inspection Date	09/09/2024
Survey held at	LBC DELIVERY PTE. LTD. - 67 TAMPINES CENTRAL 7 #15-35 CITYLIFE@TAMPINES, SINGAPORE 528598		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days