

REF: CS/LIP24090108/Avh3

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP RES / OD RES / EVA / INV / MVTo in Vehicle No: _____at W/O _____

of _____

Insured: **SMS 5987R**

Policy No: _____

Claims No: **BVS24/0530**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remarks: Vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SNK4708S** Yr Regn: **2023 April**Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Toyota Yaris Cross** Hybrid C.D. **1490**Colour: **Yellow** A/C: Insured / Std / NI / NASp. Reading: **104475** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **MXPJ103068614**Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: **205/65R15**R: **205/65R15**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. **06** mm

Rear

R/Bal. **06** mmL/Bal. **06** mmL/Bal. **06** mmD.O.A. **27/7/2024**D.O.A. **09/09/24**

Survey held at

LBC Delivery

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rees o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Liberty.**25/9/24 LS \$1100 confirmed with Didi (Red 2752.43, 71%)**

COE Expiry:

Estimate given during: Yes (✓)

1st Survey: No ()

MV: **1321K**PV: **86.7K**Nett: **45.3K**

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: **2**

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Inve (\$)) 8 + RS \$1

) Photos

) Others

Report Format: _____

E-mail: 24090108@lbc.com

LBC DELIVERY PTE. LTD.

Company Registration No. 202314690E

67 Tampines Central 7 #15-35 Citylife@Tampines, Singapore 528598

Email : lbcdelivery2023@gmail.com

Tel : 85127719

MEGA CAR LEASING

152 SERANGOON NORTH AVE 1

#04-326

SINGAPORE 550152

ESTIMATE

Accident Date: 27/07/2024

Vehicle No.: SNK4708S

Model: TOYOTA YARIS CROSS HYBRID 1.5X CVT

Chassis/Eng#: MXPJ103068614/M15AY575849

No	Description Of Parts		Qty	Unit Price	Amount
1	REAR BUMPER <i>Del'd</i>	L	1	\$ 501.70	\$ 501.70
2	REAR BUMPER LOWER LID <i>Del'd</i>	L	1	\$ 745.00	\$ 745.00
3	REAR BUMPER RH REVERSE SENSOR <i>new</i>	L	1	\$ 494.20	\$ 494.20
4	REAR BUMPER REVERSE SENSOR 'O' RING <i>new</i>	L	4	\$ 20.00	\$ 80.00
5	REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	L	4	\$ 25.00	\$ 100.00
6	REAR BUMPER RH SIDE RETAINER <i>new</i>	L	1	\$ 124.20	\$ 124.20
7	REAR BUMPER RH REFLECTOR <i>new</i>	L	1	\$ 81.80	\$ 81.80
8	REAR RH FENDER ARCH GARNISH <i>Del'd</i>	L	1	\$ 211.70	\$ 211.70
9	REAR RH TAILLAMP <i>new</i>	L	1	\$ 851.30	\$ 851.30
Subtotal before discount:					\$ 3,189.90
Percentage discount 25%:					\$ 797.48
Sub-total 1					\$ 2,392.43

10	REAR BUMPER CLIPS - SET <i>new</i>	S	1	\$ 50.00	\$ 50.00
11	REAR BUMPER '3D' ART WORK STICKER <i>new</i>	S	1	\$ 40.00	\$ 40.00
12	REAR RH FENDER ARCH GARNISH CLIPS - SET <i>new</i>	S	1	\$ 30.00	\$ 30.00
Subtotal before discount:					\$ 120.00
Percentage discount 0%:					0.00
Sub-total 2					\$ 120.00
Parts-total					\$ 2,512.43

LABOUR

1	To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	\$ 80.00
2	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	\$ 600.00
3	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	\$ 600.00
4	To apply anti-rust chemical on repaired and replaced panel.	\$ 60.00
Labour total		\$ 1,340.00
Parts & Labour total		\$ 3,852.43

Acknowledged by Repairer

Signature:

Date:

Admin
2/5 09/09/24

02 Days