

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24060147/EMA3Q2
Date: 03/09/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0007747_03
Claimant Vehicle No : SHA5725J Insured Vehicle No : SMW6454J
Date of Loss: 15/06/2024 Nature of Claim: TP Claim No: MFL2024D0007129

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA5725J
Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A) Engine No: 2ZRS063037
Reg. Date: 07/09/2017 (Man. Year: 2017) Chassis No: JTDKB3FU503563915
Colour: Blue Odometer: 661719 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,070.70	491.22	579.48	54.12
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	820.00	600.00	220.00	26.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,902.70	1,103.22	799.48	42.02
Approved Total (Overridden) (S\$)		900.00		
(S\$)	1,902.70	900.00	1,002.70	52.70
+ GST 9.00/9.00% (S\$)	171.24	81.00	90.24	52.70
Nett Amount (S\$)	2,073.94	981.00	1,092.94	52.70
+ Car Rental (4.0 x S\$114.97/day) (S\$)		459.88		
+ Loss of Earnings (4.0 x S\$40.00/day) (S\$)		160.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		1,628.13		
Global Sum Settlement (S\$)		1,600.00		

INSPECTION

Date of Assignment: 19/06/2024 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected: 19/06/2024 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969
Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jul 2024)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA5725J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	503.04 FL	*- FL
2	1		*REAR BUMPER UNDER COVER-BLACK	Cut	654.96 FL	*654.96 FL
3	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
4	1		*REVERSE SENSORS	Not Necessary	135.70 F	*- F
5	1		*REAR BUMPER MAT	Not Necessary	50.00 F	*- F
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					1,365.70	654.96
- List Item Discount on L Items 25.00/25.00% (S\$)					295.00	163.74
Total Parts (S\$)					1,070.70	491.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	R/I REVERSE SENSORS	New	120.00	0.00
Gross Labour Cost (\$\$)			820.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >