

# TSL AUTO PRO SELECTION PTE LTD

BLK 1 KAKI BUKIT AVE 6 #01-06 AUTOBAY @KAKI BUKIT  
SINGAPORE 417883

TO	: AIG	DATE	10/9/2024
VEHICLE NO	: GBL9664M (2022)	Xiao Chen.	
VEHICLE MODEL	: TOYOTA HIACE		
CHASSIS NO	: TRH2000359262		

## CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Behind</i>	1	\$ 673.10	\$ 673.10
2	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 47.20	\$ 94.40
3	REAR BUMPER LOWER BRACKET <i>new</i>	4	\$ 18.00	\$ 72.00
4	REAR BUMPER STEP PANEL <i>Dented</i>	1	\$ 288.50	\$ 288.50
5	REAR END PANEL OUTER <i>Dented</i>	1	\$ 743.20	\$ 743.20
6	REAR END PANEL INNER <i>new</i>	1	\$ 820.90	\$ 820.90
7	REAR END PANEL TOP METAL STRIPE <i>new</i>	1	\$ 288.50	\$ 288.50
8	REAR END PANEL SIDE EXTENSION <i>new</i>	2	\$ 362.10	\$ 724.20
9	TAILLAMP <i>crack</i>	2	\$ 363.40	\$ 726.80
10	TAILLAMP LOWER APRON <i>LH Behind</i>	2	\$ 86.10	\$ 172.20
11	TAILGATE <i>Dented</i>	1	\$ 2,239.60	\$ 2,239.60
12	TAILGATE LOCK <i>new</i>	1	\$ 398.50	\$ 398.50
13	TAILGATE LOCK COVER <i>new</i>	1	\$ 69.50	\$ 69.50
14	TAILGATE LOCK ACTUATOR <i>new</i>	1	\$ 399.10	\$ 399.10
15	TAILGATE WEATHERSTRIPE <i>new</i>	1	\$ 387.30	\$ 387.30
16	TAILGATE DAMPER <i>new</i>	2	\$ 364.60	\$ 729.10
17	TAILGATE HINGE <i>new</i>	2	\$ 76.10	\$ 152.20
18	TAILGATE GLASS MOULDING <i>new</i>	1	\$ 172.50	\$ 172.50
19	TAILGATE OUTER MOULDING <i>new</i>	1	\$ 298.80	\$ 298.80
20	TAILGATE INNER TRIM COVER <i>new</i>	1	\$ 165.80	\$ 165.80
21	TOYOTA LOGO <i>new</i>	1	\$ 60.80	\$ 60.80
22	HIACE STICKER <i>new</i>	1	\$ 65.60	\$ 65.60
23	1250KG STICKER <i>new</i>	1	\$ 58.50	\$ 58.50
24	SPARE TYRE CARRIAGE <i>new</i>	1	\$ 376.50	\$ 376.50

TOTAL PRICE: \$ 10,177.60

LESS 25% \$ 2,497.40

SUB TOTAL PRICE: \$ 7,492.20

*5685.80*  
*3264.42*

## SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BNUMBER PLATE <i>new</i>	1	\$ 30.00	\$ 30.00
2	REAR NUMBER PLATE HOLDER <i>new</i>	1	\$ 30.00	\$ 30.00
3	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
4	REVERSE SENSOR <i>new</i>	1 SET	\$ 280.00	\$ 280.00
5	REAR END PANEL SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00
6	TAILGATE OUTER MOULDING CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
7	TAILAGTE INNER TRIM COVER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
8	TAILGATE GLASS SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00

9	TAILGATE SURROUND MOULDING <i>HW</i>	1	\$ 200.00	\$ 200.00	<i>W</i>
10	FLOOR PANEL TOP BOARD <i>HW</i>	1	\$ 750.00	\$ 750.00	<i>X</i>
11	REAR CAMERA <i>new</i>	1	\$ 480.00	\$ 480.00	<i>X</i>
12	70KM/H STICKER <i>NW</i>	1	\$ 15.00	\$ 15.00	<i>X</i>
13	8 PAX STICKER <i>HW</i>	1	\$ 15.00	\$ 15.00	<i>X</i>
			TOTAL:	\$ 2,000.00	<i>585</i>

*Advertisement Stickers NW*

*350  
180*

**LABOUR**

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	<i>800</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	<i>700</i>	
3	WIRING CHECK	\$ 100.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>80</i>	
5	TO REMOVE UPHOLSTRY	\$ 150.00	<i>X</i>	
6	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50</i>	
7	TO REMOVE TAILGATE GLASS	\$ 180.00	<i>120</i>	
8	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	<i>60</i>	
9	TO REMOVE INNER FURNITURE	\$ 500.00	<i>X</i>	
10	TO REMOVE REAR CAMERA	\$ 100.00	<i>50</i>	
		TOTAL:	\$ 3,830.00	

*1890*

**ESTIMATE REPORT**

TOTAL PARTS COST:	\$	9,492.20
TOTAL LABOUR COST:	\$	3,830.00
TOTAL REPAIR COST:	\$	13,322.20

*total: 6738.42*

*L/S: 5.4K*

*06 Days*

*5.4K*

*NO. 1 \$1743.20  
NO. 2 \$288.50*

*L/S: \$ 5.4K*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
Signature:  
Date: