

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0281/2024
DATE : 05-SEP-2024

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : EDWARD KUNAFI
ADDRESS : BLK 13 GHIM MOH ROAD
#05-41
S(270013)
TELEPHONE NO : 96945551

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SLA9197J
VEHICLE NO : SLA9197J
MODEL CODE : BDTARCZB17EWA----A
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT)
ENGINE NO : HR16985508B
CHASSIS NO : MNTBBAB17Z0026841
MILEAGE : 1 KM
DATE IN : 05/09/2024
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 30/08/2024

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLA9197J

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	
2	RSI	R/INSTALL OR RENEW REVERSE SENSOR ASSIST TO REPAIR	55.00	
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	
4	ZZ/001	CHECK LIGHTING	48.00	
5	ZZ/002	REPAIR RR END PANEL & LH RR FENDER RENEW RR BUMPER	860.00	
6	ZZ/003	S/PAINT LH RR FENDER,RR END PANEL & RR BUMPER	1140.00	
		TOTAL LABOUR CHARGES	2323.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLA9197J

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 BUMPER	85022-3ST4H	858.60		
2 ENERGY LH ABS	85093-3ST0A	146.30		
3 STAY RR LH	85213-EE530	47.40		
4 BRACKET LH	85227-3ST1A	38.60		
5 CROMMET(\$3X2)	63846-5V000	6.00		
6 ORNAMENT ASSY L	26565-5C000	68.90		
7 LAMP COMB RR,LH	26555-3SB0A	407.90		
8 SUNDRIES	NPN			30.00
9 CLIP(\$1.5X10)	01553-05933	15.00		
SUB TOTAL		1588.70	0.00	30.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		317.74	0.00	0.00
GRAND TOTAL		1270.96	0.00	30.00
OVERALL TOTAL		1300.96		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLA9197J

TOTAL LABOUR CHARGES	2323.00
TOTAL SPARE PARTS CHARGES	1300.96

GRAND TOTAL	3623.96 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.