

WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

9 September 2024

Acknowledged by Repairer

Signature:

Date:

REG NO. : SNL8671G

MAKE/MODEL : TOYOTA HARRIER PREMIUM

Not Authorized
Morris
9/9/24
2/s & 2000/
3 days

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear Windscreen Moulding 11	\$ 85.00 X
1	Rear Tailgate R	\$ 2,598.00 X
1	Lamp RH 11	\$ 472.00 X
1	Rear Tailgate "LOGO" Emblem 11	\$ 68.50 X
1	Rear Tailgate "HARRIER" Emblem 11	\$ 78.80
2	Rear Taillamp RH 11	\$ 878.00 X
1	Rear End Panel R	\$ 818.00 X
1	Rear Bumper 11/701p	\$ 904.00 1,398.00
1	Rear Bumper Lower Diffuser 11/701p	\$ 466.00 685.00
1	Rear Bumper Reflector 11/701p	\$ 108.50 158.00
1	Rear Bumper Reinforcement 11	\$ 495.00 X
1	Rear Bumper Side Retainers 11	\$ 168.00 X
2	Rear Bumper "PDC" Sensors 11	\$ 598.00 X
1	Rear Bumper Tow Hook Cover 11	\$ 58.20 X
1	Rear Bumper Inner Sponge 11	\$ 248.50 495.00
		\$ 9,053.50
	Less 25%	\$ 2,263.38
		\$ 6,790.13

SPECIAL NETT ITEMS

1	Rear Windscreen Sealant 11	\$ 80.00 X
1	Rear Bumper Clip (1 Set) 11	\$ 78.00 50
		\$ 158.00

LABOUR CHARGES

1	To Remove, Replaced Damaged Lamps And Check Up Rear Wiring.	\$ 80.00 20
2	To Remove And Refit Rear Reverse Sensor.	\$ 180.00 30
3	To Remove And Refit Rear Windscreen Glass.	\$ 180.00 X
4	To Apply Undercoating.	\$ 200.00 X
5	Panel Beating.	\$ 1,500.00 450
6	To Re-spray Painting On The Affected Areas.	\$ 1,500.00 600
		\$ 3,640.00

GRAND TOTAL :

\$ 10,588.13

2- 1804.80
252
1354.35
50
1100
2804.35