

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/INC 2409047/4nh3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNL 86716

at Workshop m/s we garage.

of _____

Insured: FB P 86716

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$33k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

916D

Vehicle: IN / OUT

Date: _____ Person Contacted: LTAS 22864

Veh No: SNL 86716 Yr Regn: 27/11/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A/)

Make: Toyota harrier c.c 1986

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 157687 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 7SU 6000 61419

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 235/55-R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 0 mm L/Bal. mm

D.O.A. 04/09/24 D.O.I. 9/5/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
12/9/24	L/S @ 2000 inspect lawrence (Red. \$8588.13, 81%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 3

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$) \$ + RS, SI☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)

Report Format : _____

Lump Sum / I.B.I: (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	916D
Vehicle Details	
Vehicle No.:	SNL8671G
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Sep 2024
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER PREMIUM 2.0 A
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	3ZRB663041
Chassis No.:	ZSU600061419
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$29,513.00
Original Registration Date:	27 Nov 2015
First Registration Date:	27 Nov 2015
Transfer Count:	2
Actual ARF Paid:	\$28,319.00 14159
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Nov 2025
PARF Rebate Amount:	\$15,575.00
Intended COE Rebate Details	
COE Expiry Date:	26 Nov 2025
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$60,000.00
COE Rebate Amount:	\$7,269.00
Total Rebate Amount:	\$22,844.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 09 Sep 2024

OK



All Category



1

Search

Save Search



2015 X

28 Vehicles

Car Make

Car Model

Price Range

Depreciation

2015

Mileage



Toyota Harrier 2.0A Elegance Panoramic Roof **\$35,800** \$19,120 /yr 25-Nov-2015 99,400 km

Instl. \$1,979 /mth 1 Owner

Engine and gearbox run smoothly. New paintwork. Ideal for 5/10 years COE renewal. Lowest bank interest at 2.48%. 100% in house loan with guaranteed approval welcome. Cash deal most welcome. STA pre-purchase inspection welcome. Viewing daily at our showroom by appointment. Immediate transfer of ownership upon collection. Hurry now! High Speed Motor|Posted 07-Sep-2024 ☐ Compare



Toyota Harrier 2.0A Premium Panoramic Roof **\$79,800** \$15,950 /yr 10-Apr-2015

(New 5-yr COE) Instl. \$1,075 /mth 105,000 km 2 Owners

2 owners. Option 10 years COE at \$133,800, white paintwork with black leather interior. Beautifully maintained unit! Engine in stock condition! Perfect undercarriage with no abnormal sounds, view and test drive to believe! Auto Zoom Enterprise Pte Ltd|Posted 07-Sep-2024 ☐ Compare



Toyota Harrier 2.0A Premium Panoramic Roof **\$36,888** \$17,150 /yr 30-Dec-2015 N.A.

Instl. \$1,898 /mth 3 Owners

Awesome Motors Pte Ltd|Posted 06-Sep-2024 ☐ Compare



Toyota Harrier 2.0A Elegance (New 10-yr COE) **\$131,000** \$13,090 /yr 22-Jul-2015 150,000 km

Instl. \$1,302 /mth 2 Owners

Without COE Renewal \$38,888. New gearbox with receipt by reputable workshop. Brand new tyres and rims. Car well maintained by previous owner. No repair needed. 100% loan available. Bank in house loan and high trade in available. Ex bankruptcy or bad credit can apply, fast and easy loan approval! Contact our friendly consultant for a non-obligation advice. Shift 2 Drive Pte Ltd|Posted 06-Sep-2024 ☐ Compare

Compare

WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

9 September 2024

Acknowledged by Repairer

Signature:

REG NO. : SNL8671G
MAKE/MODEL : TOYOTA HARRIER PREMIUM

Not Authorized
M
M
9/9/24
2/5 @ 2000
3 days

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear Windscreen Moulding <i>11</i>	\$ 85.00 <i>X</i>
1	Rear Tailgate <i>R</i>	\$ 2,598.00 <i>X</i>
1	Lamp RH <i>11</i>	\$ 472.00 <i>X</i>
1	Rear Tailgate "LOGO" Emblem <i>11</i>	\$ 68.50 <i>X</i>
1	Rear Tailgate "HARRIER" Emblem <i>11</i>	\$ 78.80 <i>X</i>
2	Rear Taillamp RH <i>11</i>	\$ 878.00 <i>X</i>
1	Rear End Panel <i>R</i>	\$ 818.00 <i>X</i>
1	Rear Bumper <i>cut to fit</i>	\$ 904.00 <i>1,398.00</i>
1	Rear Bumper Lower Diffuser <i>gross</i>	\$ 466.00 <i>685.00</i>
1	Rear Bumper Reflector <i>o/s one</i>	\$ 108.50 <i>158.00</i>
1	Rear Bumper Reinforcement <i>11</i>	\$ 495.00 <i>X</i>
1	Rear Bumper Side Retainers <i>11</i>	\$ 168.00 <i>X</i>
2	Rear Bumper "PDC" Sensors <i>512</i>	\$ 598.00 <i>X</i>
1	Rear Bumper Tow Hook Cover <i>11</i>	\$ 58.20 <i>X</i>
1	Rear Bumper Inner Sponge <i>1011</i>	\$ 248.50 <i>495.00</i>
		\$ 9,053.50
	Less 25%	\$ 2,263.38
		\$ 6,790.13

SPECIAL NETT ITEMS

1	Rear Windscreen Sealant <i>11</i>	\$ 80.00 <i>X</i>
1	Rear Bumper Clip (1 Set) <i>11</i>	\$ 78.00 <i>50</i>
		\$ 158.00

LABOUR CHARGES

1	To Remove, Replaced Damaged Lamps And Check Up Rear Wiring.	\$ 80.00 <i>20</i>
2	To Remove And Refit Rear Reverse Sensor.	\$ 180.00 <i>30</i>
3	To Remove And Refit Rear Windscreen Glass.	\$ 11 180.00 <i>X</i>
4	To Apply Undercoating.	\$ 11 200.00 <i>X</i>
5	Panel Beating.	\$ 1,500.00 <i>450</i>
6	To Re-spray Painting On The Affected Areas.	\$ 1,500.00 <i>600</i>
		\$ 3,640.00

GRAND TOTAL :

Page 1 of 1

\$ 10,588.13

2- 1806.80
252
1354.38
50
1100
2804.38