

EM Solution Pte Ltd

160 Sin Ming Drive #03-19, Sin Ming Autocity
Singapore 575722
Tel: 64560226
GST/Reg. No: 201016308K

ESTIMATE

Date : 9th Sept 2024

Mdm Tay Bee Wah

Blk 157 Lorong 1 Toa Payoh #09-1239
Singapore 310157

Veh No : SNE 8044D

Make/Model : Mini One

Chassis No : WMWXS12030T819270

Date of Acc : 03.09.24

TP Veh No : SBS 3974X

Not Withheld
11 Rm & 2350/-
Repair After Rain
2 days

S/No	Qty	Description	Unit Price	Amount
Materials				
1	1 pc	Rear Bumper 1268.70	Delcom \$	1,614.60 ✓
2	1 pc	Rear Bumper Side Guide LH	cm \$	284.00 2
3	1 pc	Rear Bumper Lower Garnish 296.40	my cm \$	490.00 2
4	2 pcs	Rear Lamp L/R C410 olisu X	493.00 \$	986.00 2X
5	2 pcs	Rear Lamp Chrome Rim L/R	128.00 \$	256.00 2X
6	1 pc	Rear Fender Wheel Arch LH 153.20	my cm \$	286.00 2
				\$ 3,916.60
				Less 5% \$ 195.83
Parts Total :				\$ 3,720.77
Special Nett				
1	1 set	Rear Bumper Clips	\$ 55.00	✓
2	1 set	Reverse Sensor	\$ 250.00	X
Special Nett :				\$ 305.00
Labour				
1		To remove & rearrange electrical wirings, check lightings	\$ 80.00	201
2		To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident.	\$ 400.00	2001
3		Putty and respray painting on affected portions.	\$ 400.00	2201
4		To remove & renew reverse sensor	\$ 80.00	501
5		Rust proofing on affected portions.	\$ 100.00	X
Labour Total :				\$ 1,060.00
Total Parts & Labour :				\$ 5,085.77

for EM Solution Pte Ltd

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: