

ASS. REC. BY:

REF: SmolKenneth**ASSIGNMENT**

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$209K

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 04 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No: PNN 9491SYr Regn: 12, 23

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

(A)WagenMake: Toy Voxyc.c. 1797Colour: M.P. white

A/C: Insured / Std / NI / NA

Sp. Reading: 64277

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

ZWR 90 - 0135298Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size: F: Giti 205/55 R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 86 mmR/Bal. 8 mmL/Bal. 86 mmL/Bal. 8 mmD.O.A. 4/9/24D.O.I. 11/9/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 for body

The U/C / Chassis frame / Body Structure affected due to collision.

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S - RS. SI

Fees

Others

TOTAL

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Report Format :

ump Sum / I.B.I. (\$



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 6/9/2024
VEHICLE : SNN9491S
MAKE/MODEL : TOYOTA VOXY
CHASSIS NO : ZWR90-0135298
MILLAGE : 62100KM
TYRE SIZE :
DOA : 4/9/2024

Not Authorised
11 May 8
Penny After Rain
4 days

List items

01 PC	RH SIDE MIRROR ASSY (Complete) Pr?	nd/Bn	\$ 8,565.95	✓
01 PC	RH SIDE MIRROR COVER	\$ R	214.75	X
01 PC	FRONT RH FENDER	\$ R	1,657.95	X
01 PC	FRONT RH FENDER INNER SHIELD	\$ R	422.10	X
01 PC	FRONT RH FENDER INNER GANISH	\$ R	152.70	X
01 PC	FRONT BUMPER	\$	3,289.80	7
01 PC	FRONT RH HEAD LAMP	\$ R	11,359.20	X
01 PC	FRONT RH HEAD LAMP BRACKET	\$ R	720.00	X
01 PC	FRONT BUMPER GRILLE ASSY	1 in Rm/Bn	3,774.00	X
01 PC	FRONT BUMPER GRILLE CHROME MOULDING RH TOP	678 Rm	297.95	✓
01 PC	FRONT BUMPER GRILLE CHROME MOULDING RH SIDE	\$ Rm	347.60	✓
01 PC	FRONT BUMPER GRILLE CHROME MOULDING RH LOW	678 Rm	347.60	✓
01 PC	WIPER TANK NECK	\$ Rm	179.45	X
01 PC	WIPER TANK	\$ Rm	424.70	X
01 PC	FRONT REINFORMENT	\$ R	980.75	X
01 PC	FRONT REINFORMENT FOAM	\$ Rm	288.00	X
01 PC	FRONT LOWER REINFORMENT	\$ R	540.05	X
01 PC	FRONT LOWER REINFORMENT FOAM	\$ Rm	288.00	X
01 PC	FRONT RH RETAINER	\$ Rm	229.05	X
01 PC	FRONT RH KNCKLER	\$ Rm	1,013.15	X
01 PC	FRONT RH WHEEL BEARING	\$ Rm	720.00	X
01 PC	FRONT RH LOWER ARM	\$ Rm	651.75	X
01 PC	FRONT RH ABSORBER	\$ Rm	993.15	X
TOTAL PARTS COST			\$ 37,457.65	

259

Special Nett Item:

06 PC	FRONT BUMPER CLIP @ \$8	\$ Rm	48.00	✓
08 PC	FRONT FENDER INNER SHIELD CLIP @ \$8	\$ Rm	64.00	X
02 PC	FRONT PARKING SENSOR @ \$280	\$ Rm	560.00	X
01 PC	FRONT RH RIM	\$ Rm	800.00	X
01 PC	FRONT RH TYRES	\$ Rm	250.00	X
			\$ 1,722.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA
3. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS
5. TO SUPPLY LABOUR TO REMOVE AND REFIX UNDERCARRAGE
6. TO SUPPLY LABOUR TO CONDUCT WHEEL BALANCING
7. TO SUPPLY LABOUR TO CONDUCT WHEEL ALIGNMENT
8. TO SUPPLY COMPUTER TO DIAGNOSTIC & REPROGRAMMING

\$	1,200.00	4001
\$	900.00	5001
\$	na	250.00 X
\$	200.00	201
\$	na	250.00 X
\$	na	50.00 X
\$	na	120.00 X
\$	450.00	7
\$	3,420.00	

TOTAL PARTS

SPECIAL NETT ITEM

TOTAL LABOUR

TOTAL COST OF REPAIR

\$	37,457.65
\$	1,722.00
\$	3,420.00
\$	42,599.65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____