

ASS. REC. BY:

REF:

ICS/

CS/ICS24090121/knp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

10/9 21:50 @ 3900k Carhu (Red. \$4883.58, 55%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

05/09/2024

Owner: AUTOGALLERY @ JDM

ESTIMATE TO REPAIR TOYOTA SIENTA HYBRID - SNN6531E

1pc	rear tailgate				R	\$ 1,358.50	✓
1pc	rear tailgate "HYBRID" emblem				rn	\$ 89.50	✓
1pc	rear tailgate "TOYOTA" emblem				rn	\$ 75.20	X
1pc	rear tailgate outer garnish				rn	\$ 485.20	X
1pc	rear tailgate inner lock				rn	\$ 425.50	X
1pc	rear tailgate inner rubber	290			nd/di	\$ 381.90	✓
1pc	rear tailgate inner cardboard				rn	\$ 281.50	X
1pc	rear tailgate inner handle				rn	\$ 121.50	X
1pc	rear tailgate windscreen moulding				rn	\$ 181.50	✓
1pc	rear LH taillamp	581.50			rn	\$ 685.20	✓
1pc	rear bumper	585			Bu	\$ 1,125.20	✓
2pcs	rear bumper side reflector @\$132.10	95				\$ 264.20	✓
8pcs	rear bumper clip @\$5.00				rn	\$ 40.00	✓
1pc	rear bumper towing cover				rn	\$ 85.20	X
2pcs	rear bumper centre parking sensor @\$258.50				nd/di	\$ 517.00	✓
4pcs	rear bumper centre parking sensor base @\$85.50	63			rn	\$ 342.00	✓
1pc	rear end panel outer				R	\$ 564.20	✓
1pc	rear end panel outer sensor				rn	\$ 281.50	X
1pc	rear end panel inner				rn	\$ 781.45	X
1pc	rear end panel inner garnish	250			rn	\$ 371.85	✓
						\$ 8,458.10	
less 25%						\$ 2,114.53	
						\$ 6,343.58	

1set rear number plate & casing

s.nett \$ 50.00 X

remove & refix rear windscreen glass

sealant

tuffkote

wiring

spray painting

labour charges

Total

\$ 150.00	120L
\$ 80.00	40L
\$ 80.00	60L
\$ 80.00	20L
\$ 1,000.00	660L
\$ 1,000.00	600L
\$ 8,783.58	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: